



Umstead Correctional Center Building Assessment



Prepared for
The Town of Butner, North Carolina

12-18-19

Prepared by

Tony Conner

HagerSmith Design

Table of Contents

Building Identification Map

Executive Summary

Specific Building Observations

Residence #1

Walls, Windows and Doors

Floor

Roof

Overall Assessment

Photographs

Residence #2

Walls, Windows and Doors

Floor

Roof

Overall Assessment

Photographs

Dormitory #3 and #4

Walls, Windows and Doors

Floor

Roof

Overall Assessment

Photographs

Shop/Facilities #5

Walls, Windows and Doors

Floor

Roof

Overall Assessment

Photographs

Gymnasium/Classroom #6

Walls, Windows and Doors

Floor

Roof

Overall Assessment

Photographs

Dormitory #7

Walls, Windows and Doors

Floor

Roof

Overall Assessment

Photographs

Administration, Cafeteria, Classroom #8

Walls, Windows and Doors

Floor

Roof

Overall Assessment

Photographs

Dormitory #9

Walls, Windows and Doors

Floor

Roof

Overall Assessment

Photographs

Structural Assessment

HagerSmith Design

Electrical and Mechanical Assessment

Bass Nixon and Kennedy

Hazardous Materials Survey Report Attachment A

Brumbaugh – Herrick, Inc. (provided by the State of North Carolina, 1996)

Roof Condition Assessment Attachment B

Curtis Construction

Roof Replacement Quote for the Gymnasium Attachment C

Curtis Construction

Demolition Quote for the Campus Attachment D

D.H. Griffin

Conclusion

HagerSmith Design

Executive Summary

This Conditions Assessment was prepared for the Town of Butner, NC as a tool for determining future work needed to bring the building into compliance with applicable codes as well as practical functionality. The report will also suggest other options for future development of the property.

Assessment of the existing conditions was carried out in October thru November of 2019 by professional staff of HagerSmith Design, PA, Bass Nixon and Kennedy, Legacy Builders, and previously by Brumbaugh – Herrick, Inc.

There are basically nine individual buildings on this site with a couple of ancillary spaces. Four of the buildings are connected with covered walkways. Two of the buildings are residential dwellings. For use in this report, the buildings will be referred to by numbers, One - Nine. Reference the aerial map for numbering.

Buildings one and two, residential dwellings, are both Type V (wood) building types. Building one residence is clad with wood siding, masonry and an asphalt shingle roof. Building two of the residence structures is brick veneer with a small wood sided porch and an asphalt shingle roof.

Buildings three and four are Type V (wood and masonry) building types. Each of these buildings have load bearing masonry exterior walls and wood framed/truss roof structures. The roof appears to have been a built-up roof system. Both of these buildings are also in extremely poor condition and are dangerous as they sit today.

Building five, the Shop/Facilities building is a Type II (non-combustible construction) building type. It is comprised of masonry exterior walls and steel truss roof supports with a flat membrane roof.

Building six, the gymnasium/classroom building is a Type II (non-combustible construction) building type. It has masonry walls, steel roof trusses/joist and a membrane roof. This building has a large gymnasium floor (VCT tile) and smaller spaces surrounding the floor.

Building seven, eight and nine are presumable Type V (some wood framing) building types. These buildings have masonry walls and metal roof joist. These buildings have a fairly new metal roof system. It is unknown how the new metal roof system installed by the State was built but we suspect there is wood framing supporting the metal.

None of the buildings listed above are sprinkled but some do have new fire alarm wiring without any devices. The buildings had been heated with a central boiler system and there were a few older chillers. The residence buildings were heated and cooled with split system heat pumps.

Specific Building Observations

Residence #1

Walls, Windows and Doors

The exterior wall construction for this structure consist of wood siding and masonry end walls. The windows are wood framed with single pane glass. The doors are wood and wood louver doors. The wood siding is in fair condition and the brick portions of the wall are in good condition. The windows and doors are in poor condition and are showing signs of water damage and decay. Signs of water leakage is evident at the window/frame connections and at the floor level of the exterior doors.

Floor

The floor appears to be a concrete slab on grade with a tile floor. No specific comments were noted.

Roof

The roof is an asphalt shingle roof that is showing signs of failure. Debris and shingle deformities are evident on the roof. Our team was not able to gain access inside the building but based on the teams through the window visual inspection there were some signs of leakage, but no major leaks were observed.

Overall assessment

This structure is in immediate need of repairs. It is unclear what damage may exist in the floor system or in the interior framing. A complete interior gut will most likely have to take place in order to mediate the mold and mildew damage. All door and windows will have to be replaced and a new roof, including some underlayment will also have to be replaced in order to save the structure from further decay. Further inspections will be required to ensure no termite damage exist.

Photographs

Images of this structure are on the next 2 pages.





Residence #2

Walls, Windows and Doors

The exterior wall construction for this structure consist of brick and wood siding. The windows are wood framed with single pane glass. The doors are wood. The wood siding is in poor condition and the brick portions of the wall are in fair to good condition. The windows and doors are in poor condition and are showing signs of water damage and decay. Signs of water leakage is evident at the window/frame connections. The exterior doors are in poor condition due to water damage and lack of maintenance.

Floor

The floor system is wood framed over a crawl space. The floor is in extremely poor to non-existent condition. Due to water intrusion the floor system is not safe or usable. There are major holes in the floor and the remaining floor system is close to collapse.

Roof

The roof is an asphalt shingle roof that is failing. Debris and shingle deformities are evident on the roof. Our team was not able to gain access inside the building but based on the teams through the window visual inspection there were some major signs of leakage.

Overall assessment

This structure is beyond practical repair and should be demolished.

Photographs

Images of this structure are on the next 2 pages.



Dormitory #3 and #4

Walls, Windows and Doors

The exterior wall construction for this structure is load bearing masonry. The windows are metal framed with single pane glass. The doors are wood and metal. The windows and doors are in poor condition and are rusting or have water damage. Signs of water leakage is evident at the window/frame connections. The exterior doors are in poor to non-existent condition. Generally, the exterior wall is in fair condition although signs of water intrusion are evident.

Floor

The floor system is a concrete slab on grade with tile floors. The condition of the slab is unknown due to the amount of building debris from furnishings and the roof. The tile has been soaked with water and is no longer adhered to the slab.

Roof

The roof is an asphalt built up roof. The roof has failed and has collapsed in many locations. In locations that have not collapsed the wood structure is beyond the point of repair and will need to be replaced.

Overall assessment

These structures are beyond practical repair and should be demolished.

Photographs

Images of this structure are on the next 3 pages.







Shop and Facilities #5

Walls, Windows and Doors

The exterior wall construction for this structure consist of brick and block. The windows are aluminum framed with insulated pane glass. The doors are storefront and metal. The windows and doors are in fair condition and are rusting or have water damage. Signs of water leakage is evident at the exterior wall/roof intersection and interior to the roof in several places. The exterior sectional doors are in poor condition. Generally, the exterior wall is in fair condition although signs of water intrusion are evident.

Floor

The floor system is a slab on grade and is in generally good condition except for being wet from the various leaks in the roof and walls.

Roof


The roof is a membrane roof of some type. The structure for the roof is steel joist and is a single slope to the rear. Signs of water leakage is evident at the exterior wall/roof intersection and interior to the roof in several places.

Overall assessment

This structure is in fair condition and could be repaired for future use. Mold and mildew remediation must occur once any leaks have been repaired.

Photographs

Images of this structure are on the next 2 pages.





Gymnasium #6

Walls, Windows and Doors

The exterior wall construction for this structure consist of brick and block with a metal panel soffit facia. The windows are metal, and aluminum framed with mostly insulated pane glass. The doors are hollow metal and metal. The windows and doors are in fair condition with some insulated glass panels that have broken seals. Generally, the exterior wall is in fair condition although signs of water intrusion are evident. There are several areas of the soffit that the facia has fallen off and has been exposed to the weather for some time. These areas will have to be repaired or completely replaced.

Floor

The floor system is a slab on grade and over the mechanical tunnel/crawl space system and is in generally good condition. There is a mix of terrazzo and VCT tiles that make up the floor finish.

Roof


The roof system is a membrane of some type, most likely EPDM/TPO and built up roof combination. The structure for the roof is steel joist. The roof is leaking in some areas throughout the building. Insulation will most likely have to be replaced due to moisture content during any roof replacement.



Overall assessment


This structure is in fair condition and could be repaired for future use. Mold and mildew remediation must occur once any leaks have been repaired.

Photographs

Images of this structure are on the next 4 pages.









Dormitory #7

Walls, Windows and Doors

The exterior wall construction for this structure consist of brick and block. The windows are metal framed with non-insulated pane glass. The doors are hollow metal and metal. The windows and doors are in poor condition with signs of water and rust damage. Generally, the exterior wall is in fair condition although signs of water intrusion are evident.

Floor

The floor system is an elevated slab and over a partial crawl space and is in generally good condition. There are VCT tiles that make up the floor finish.

Roof


The roof system has been capped with a metal roof system. The framing for this roof is unknown but is probably wood framing. Our opinion is that the original built up roof system still exist under the new metal roof installation.

Overall assessment

This structure is in fair condition and could be repaired for future use. There is evidence of water damage throughout the building. This damage most likely occurred prior to the installation of the new metal roof. Mold and mildew remediation must occur once any leaks have been repaired.

Photographs

Images of this structure are on the next 3 pages.







Administration/Classroom #8

Walls, Windows and Doors

The exterior wall construction for this structure consist of brick and block. The windows are metal framed with non-insulated pane glass. The doors are hollow metal and metal. The windows and doors are in poor condition with signs of water and rust damage. Generally, the exterior wall is in fair condition although signs of water intrusion are evident.

Floor

The floor system is an elevated slab and over a partial crawl space and is in generally good condition. There are VCT tiles that make up the floor finish. There are several windows that have been broken and remain open.

Roof

The roof system has been capped with a single sloped metal roof system. The framing for this roof is unknown. Our opinion is that the original built up roof system still exist under the new metal roof installation.

Overall assessment


This structure is in fair condition and could be repaired for future use. There is evidence of water damage throughout the building. This damage most likely occurred prior to the installation of the new metal roof. Mold and mildew remediation must occur with any repairs.

Photographs

Images of this structure are on the next 4 pages.









Dormitory #9

Walls, Windows and Doors

The exterior wall construction for this structure consist of brick and block. The windows are metal framed with non-insulated pane glass. The doors are hollow metal and metal. The windows and doors are in poor condition with signs of water and rust damage. Generally, the exterior wall is in fair condition although signs of water intrusion are evident.

Floor

The floor system is an elevated slab and over a partial crawl space and is in generally good condition. There are VCT tiles that make up the floor finish.

Roof


The roof system has been capped with a metal roof system. The framing for this roof is unknown but is probably wood framing. Our opinion is that the original built up roof system still exist under the new metal roof installation.

Overall assessment

This structure is in fair condition and could be repaired for future use. There is evidence of water damage throughout the building. This damage most likely occurred prior to the installation of the new metal roof. Mold and mildew remediation must occur once any leaks have been repaired.

Photographs

Images of this structure are on the next page.



Structural Assessment

Based on our visual walk-thru for the buildings we offer the following opinions regarding structural soundness. The following comments are broken down per individual structure.

Residence #1

Our team was not allowed access to this structure but based on our visual inspection from outside there appeared to be minimal water damage to structural elements. However, a thorough inspection will have to be performed in order to assess the structure from a termite activity perspective. The floor is a slab on grade. The rest of the structure is wood framing and wood trusses.

Residence #2

Our team was not allowed access to this structure but based on our visual inspection from outside there appeared to be major water damage to structural elements. This residence is a conventionally built residential wood structure. There has been catastrophic damage done to the roof, floor and walls. This building is unsafe and not structurally sound.

Dormitory #3

Our team was not allowed access to this structure but based on our visual inspection from outside there appeared to be major water damage to most components of the building. This building has structural load bearing exterior walls and a concrete slab on grade floor. The roof construction is wood with a built-up roof membrane. There has been catastrophic damage done to the roof and interior walls due to the failure of the roof. This building is unsafe and not structurally sound.

Dormitory #4

Based on our visual inspection there was major to most components of the building. This building has structural load bearing exterior walls and a concrete slab on grade floor. The roof construction is wood with a built-up roof membrane. There has been catastrophic damage done to the roof and interior walls due to the failure of the roof. This building is unsafe and not structurally sound.

Shop/Facilities Building #5

Based on our visual inspection there were no major deficiencies to structural elements. This building has structural load bearing exterior walls, a concrete slab on grade floor and a light-weight steel frame with bar joist. While there has been water infiltration into the building the materials used for the structure have not sustained substantial damage.

Gymnasium/Classroom #6

Based on our visual inspection there were no major deficiencies to structural elements. This building has structural load bearing interior and exterior walls, a concrete slab on grade floor and metal bar joist roof supports. While there has been water infiltration into the building the materials used for the structure have not sustained substantial damage. An inspection was not conducted in the tunnel system/crawl space that is under the building, but no significant settlement was found.

Dormitory #7

Based on our visual inspection there were no major deficiencies to structural elements. This building has structural load bearing interior and exterior walls, a concrete slab on grade floor and metal bar joist roof supports. While there has been water infiltration into the building the materials used for the structure have not sustained substantial damage. An inspection was not conducted in the crawl space under the building, but no significant settlement was found.

Administration/Classroom Building #8

Based on our visual inspection there were no major deficiencies to structural elements. This building has structural load bearing interior and exterior walls, a concrete slab on grade and elevated floor and metal bar joist roof supports. While there has been water infiltration into the building the materials used for the structure have not sustained substantial damage. An inspection was not conducted in the crawl space under the building, but no significant settlement was found.

Dormitory #9

Based on our visual inspection there was no major deficiencies to structural elements. This building has structural load bearing interior and exterior walls, a concrete slab on grade floor and metal bar joist roof supports. While there has been water infiltration into the building the materials used for the structure have not sustained substantial damage. An inspection was not conducted in the crawl space under the building, but no significant settlement was found.

Electrical, Mechanical and Plumbing Assessment

Based on our visual walk-thru for the buildings we offer the following opinions regarding Electrical, Mechanical and Plumbing systems. The following comments are not broken down per individual structure. These are blanket statements for all buildings. These opinions are based on experience working with existing systems of these types in buildings of this age and condition.

Electrical Systems

All electrical systems should be demolished and rebuilt to current code and safety standards from the service point (Power company transformer). This opinion is based on the condition of the existing systems observed and the conditions, or non-conditions, that the systems have been kept.

Mechanical Systems

There are no mechanical systems that are salvageable. All boilers, chillers, heat pumps and related equipment will have to be demolished and replaced with code compliant systems. In addition to the actual mechanical units, all ductwork and associated piping will have to be replaced as well. This opinion is based on the age of the inactive systems and the conditions, or non-conditions, that the systems have been kept.

Plumbing System

All plumbing fixtures should be replaced. A detailed investigation should be run regarding the main drain lines to the SGWASA sewer system. Our experience has shown that the probably cast-iron pipes (they could be clay tile) that serve these structures has degraded beyond repair. The waterlines that serve the structures are, in our opinion also no longer serviceable and should be replaced.

Summary

All electrical, mechanical and plumbing systems will be required to be rebuilt from scratch to serve the building in a safe and code compliant manner.

Hazardous Materials Survey Report

Attachment A

Gymnasium Roof Condition Assessment

Attachment B

Gymnasium Roof Replacement Quote

Attachment C

Campus Demolition Quote

Attachment D

Conclusion

Based on the assessment teams finding, our opinions are as follows:

Buildings #1, #2, #3 and #4 are beyond the point of practical renovation. These buildings would best be demolished to regain the land that they currently sit on. Of the 4 buildings listed, building #1 has the most potential to be saved, however it would take significant renovations to render the building habitable. We estimate an investment of approximately \$175,000 to \$200,000 to renovate this building up to a point that it could be considered as a rental property. Building #2 has reached the point of no return in the team's opinion. It is not practical to spend any funds to save the structure. Building #3 and #4 are also beyond practical renovations. The renovation cost for these buildings is approximately between \$250 and \$275 per square foot. New buildings of this same square footage would cost approximately \$200 to \$250 per square foot. **The total investment to renovate buildings #3 and #4 would be approximately \$3,353,600. Two new buildings of the same square footage would be approximately \$2,880,000.**

Building #5, the Shop/Facilities Building is arguably the building that has the most potential, as it sits. The renovation of this building would include a roof replacement at a cost of approximately \$50,000. In addition to the roof replacement we estimate a renovation cost of \$100 to \$125 per square foot. This estimate includes renovation to bring the building back to its original use. **The total investment for this building would be approximately \$675,000.**

Buildings #6, #7, #8 and #9 are in fair condition and could be renovated for approximately \$250 to \$300 per square foot, depending the type of mechanical system installed. The main issue with these buildings is that the load bearing walls will adversely affect the future layout of the space. Due to this inflexibility it would be very difficult to upfit spaces that could effectively be used. In addition, the common space created by the large corridors and open areas would drive the rental factor too high to be sustainable. The total square footage of these buildings is approximately 61,000 square feet. **The total investment to renovate these buildings would be approximately \$16,775,000.**

The total to renovate all buildings except building #2 would be approximately \$21,000,000.

The total investment to demolish the structures listed above would be approximately \$695,000 plus asbestos remediation.

Assuming the Town could lease the leasable spaces for \$13 per square foot, not including investment cost, management and upkeep, the annual income would be approximately \$624,000. At that rate it would take **35 + years** for the investment to break even.

It is the Assessment Team's opinion that it would be in the best interest of investment to demolish the buildings on the campus. This could be done in one of two ways. Either the Town could demolish the buildings and develop Town owned uses for the site, or the Town could develop an RFP for developers to respond to. The RFP could require the developer to demolish the buildings prior to development of the site.

This concludes the assessment for the Umstead Correctional Center Campus,



Tony Conner

President

HageSmith Design

FACILITY ASBESTOS INSPECTION REPORT

For:

Umstead Correctional Center

Facility Name

4255

Facility Number

April, 1996

Date of Inspection

This inspection was conducted by an inspector accredited
in the State of North Carolina.

Inspection and Report by:

Jeffrey P. Kramer

11351
Accreditation #


Signature

Brumbaugh-Herrick, Inc.
3861 Monroe Street
Toledo, OH 43606



Brumbaugh-Herrick, Inc.

3861 Monroe Street Toledo, Ohio 43606 Tel (419)475-1253 Fax (419)475-0163

MEMORANDUM

To: Mr. Joseph A. Simpson
Director, Safety & Environmental Health
NC Department of Correction

From: Jeff Kramer
Brumbaugh-Herrick, Inc.

Subject: Umstead Building List Update

Old List

Administration Bldg. -----OK-----
Staff Housing -----Now Known As-----
Staff Housing -----Now Known As-----
Industrial Arts Bldg. -----Now Known As-----
Supt's House -----OK-----
Wood Bldg./Gym -----OK-----
Warehouse -----OK-----
Duplex 1-2 -----OK-----

New List

Administration Bldg.
Staff Housing A
Staff Housing B
Maintenance Shop
Supt's House
Wood Bldg.
Warehouse
Duplex 1-2

Also Add: A Dormitory
B Dormitory

Asbestos Inspection Survey Report - Umstead Correctional Center

Introduction

This work is being performed by Brumbaugh-Herrick, Inc. under contract to the North Carolina Department of Correction. The purpose of this inspection is to identify the Asbestos Containing Building Materials (ACBM) in all pre-1981 buildings at the Umstead facility for compliance with the OSHA asbestos standards 29 CFR 1910.1001 and 29 CFR 1926.1101. The information obtained from this report may subsequently be used to help reduce the risk of potential asbestos exposure to employees. Sampling and analysis were conducted in accordance with the state of the art inspection methods detailed in the EPA AHERA asbestos regulation [40 CFR 763 Subpart E-763.80 - 763.99] as referenced in the OSHA standard for General Industry 1921.1001 (j)(8)(ii)(B).

Summary of Results

This is the report for the asbestos inspection survey which was conducted on April 8th, 1996 at the Umstead Correctional Center in Butner, North Carolina. Certain materials were found to contain asbestos in parts of the facility. A table which lists these materials follows this page. Color coded drawings show the location of these materials in buildings larger than 2,500 square feet.

The materials are identified by building, room or location, an assigned homogeneous area identification number, the type and quantity of material, the percentage of asbestos they contain, the condition of the material and whether it is friable or non-friable. A glossary of the Type of Material Codes is an appendix to this report. A homogeneous area is the location of a material which is uniform in color, texture, size and time of installation. The condition of the material is rated as Good, Fair or Poor. Friability is a term used to describe whether a material may be crumbled or reduced to powder by hand pressure.

**Waste Management Center
Confirmed Asbestos Containing Materials**


Building	Room	IA #	Type	Material Description	Size	Cond	Friable	Asb 1	Asb 2	Z		
A Dora	Basement/Crawlspace Throughout	0318	MAG	Magnesia insulation on pipes	600 LF	F	Y	Chry	5	Amos	25	
		026	FT	12" beige speckled	3,400 SF	G	N	Chry	2			
		026A	FTM	Mastic for floor tile 026	3,400 SF	G	N	Chry	15			
	A Staff House	closets	028	MAG	Magnesia insul on pipes	300 LF	GF	Y	Chry	20	Amos	15
			034	FT	9" green w/yellow streaks	950 SF	G	N	Chry	18		
		Various	034A	FTM	Mastic for floor tile 034	950 SF	G	N	Chry	5		
			032	FT	9" brown w/yellow streaks	690 SF	G	N	Chry	15		
			032A	FTM	Mastic for floor tile 032	690 SF	G	N	Chry	10		
			033	FT	9" black w/yellow streaks	530 SF	G	N	Chry	10		
			033A	FTM	Mastic for floor tile 033	530 SF	G	N	Chry	15		
			036	FT	9" gray w/streaks	280 SF	G	N	Chry	12		
			036A	FTM	Mastic for floor tile 036	280 SF	G	N	Chry	10		
			037	FT	9" tan w/dark streaks	140 SF	G	N	Chry	8		
037A	FTM	Mastic for floor tile 037	140 SF	G	N	Chry	5					
038	FT	9" brown/yellow streaked	360 SF	G	N	Chry	8					
A Staff House/Boiler Room Administration	Boiler Room	038A	FTM	Mastic for floor tile 038	360 SF	G	N	Chry	15			
		039A	FTM	Mastic for floor tile 039	100 SF	G	H	Chry	15			
	Boiler Room	040	LN	brown/gold block pattern linoleum	260 SF	G	H	Chry	40			
		042	FT	9" brick red w/tan streaks	200 SF	G	N	Chry	8			
	Dining Patch	042A	FTM	Mastic for floor tile 042	200 SF	G	N	Chry	5			
		043	FT	9" gray w/multi-colored streaks	420 SF	G	H	Chry	8			
	Dining, Stairwells Throughout	043A	FTM	Mastic for floor tile 043	420 SF	G	H	Chry	10			
		044	LP	Layered paper pipe insulation	75 LF	F	Y	Chry	60			
	Dining, Stairwells Throughout	008	MAG	Mag insulation on steam lines	350 LF	G	Y	Amos	30			
		010	MAG	Mag insulation on hot H2O tank	100 SF	G	Y	Chry	40			
	Throughout 1st floor	007	FT	9" blue w/green streaks	40 SF	G	H	Chry	2			
		007A	FTM	Mastic for floor tile 007	40 SF	G	N	Chry	5			
	Throughout 1st floor	004	FT	9" beige w/brown flecks	1,325 SF	G	H	Chry	4			
011		MAG	Magnesia pipe insulation	2,000 LF	G	Y	Chry	10	Amos	20		
Throughout 2nd floor	016	MUD	Mud fittings on steam/water lines	400 EA	G	Y	Chry	60				
	001	FT	12" beige speckled	6,000 SF	G	H	Chry	2				
Throughout 2nd floor	001A	FTM	Mastic for floor tile 001	6,000 SF	G	H	Chry	5				
	013	FT	9" brown w/streaks	3,300 SF	G	H	Chry	10				
		013A	FTM	Mastic for floor tile 013	3,300 SF	G	N	Chry	10			

**Winstead Correctional Center
Confirmed Asbestos Containing Materials**

Building	Room	UA #	Type	Material Description	Size	Cond	Friable	Asb 1	Z	Asb 2	Z
B Dorm	Throughout	017	FT	12" beige speckled	4,000 SF	C	H	Chry	3		
		017A	FTH	Mastic for floor tile 017	4,000 SF	G	N	Chry	15		
		019	HAG	flay insulation on steam pipes	900 LF	G	Y	Chry	25	Asos	10
		020	MUD	Mud fittings on hot H2O lines	150 EA	G	Y	Chry	60		
		055	FT	9" green w/yellow streaks	520 SF	G	N	Chry	8		
		055A	FTH	Mastic for floor tile 055	520 SF	G	N	Chry	10		
		056	FT	9" brown w/multi-colored streaks	630 SF	GF	N	Chry	8		
		056A	FTH	Mastic for floor tile 056	630 SF	GF	N	Chry	10		
		057	FT	9" black w/white streaks	480 SF	G	H	Chry	10		
		057A	FTH	Mastic for floor tile 057	480 SF	G	H	Chry	10		
B Staff House	Various Rooms	058	FT	9" gray w/light & dark streaks	280 SF	G	H	Chry	10		
		058A	FTH	Mastic for floor tile 058	280 SF	G	H	Chry	10		
		059	FT	9" brown w/yellow streaks	280 SF	P	N	Chry	12		
		059A	FTH	Mastic for floor tile 059	280 SF	P	N	Chry	12		
		060	FT	12" white w/black streaks	700 SF	GF	H	Chry	2		
		060A	FTH	Mastic for floor tile 060	700 SF	GF	H	Chry	2		
		062	FT	9" gray w/multi-colored streaks	700 SF	GF	N	Chry	5		
		062A	FTH	Mastic for floor tile 062	630 SF	G	H	Chry	15		
		063	FT	9" beige w/dark streaks	630 SF	G	N	Chry	20		
		063A	FTH	Mastic for floor tile 063	470 SF	G	N	Chry	10		
B Staff House/Boiler Rm	Boiler Room	064	FT	9" red w/light streaks	470 SF	G	H	Chry	20		
		064A	FTH	Mastic for floor tile 064	130 SF	G	N	Chry	12		
		066	LP	Layered paper pipe insulation	130 SF	G	H	Chry	15		
		067	MUD	Mudded insul on FG pipe insul	55 LF	FP	Y	Chry	60	Asos	2
		052	TP	Transite Panels	10 EA	G	Y	Chry	15		
		050	FT	12" white w/beige streaks	380 SF	GF	N	Chry	55		
		050A	FTH	Mastic for floor tile 050	2,100 SF	G	N	Chry	2		
		069	FT	12" gold w/brown streaks	2,100 SF	G	N	Chry	5		
		069A	FTH	Mastic for floor tile 069	530 SF	G	N	Chry	2		
		048	TP	Transite Panels	530 SF	G	N	Chry	10		
Duplex	Furnace Rooms Throughout	047	LN	Green linoleum	190 SF	F	N	Chry	55		
		072	MUD	Mud fittings on old FG pipe insul	280 SF	F	H	Chry	5		
Maintenance Bldg	Office/Lobby/Tool Rm	074	FT	9" beige w/brown streaks	100 EA	G	Y	Chry	40		
		074A	FTH	Mastic for floor tile 074	2,750 SF	G	N	Chry	4		
Supt's Residence	Furnace Room Kitchen/Back Porch	074	FT	9" beige w/brown streaks	2,750 SF	G	N	Chry	10		
		074A	FTH	Mastic for floor tile 074	2,750 SF	G	N	Chry	10		
Food Building	Bowling/Various Offices/Class	074	FT	9" beige w/brown streaks	2,750 SF	G	N	Chry	4		
		074A	FTH	Mastic for floor tile 074	2,750 SF	G	N	Chry	10		

**Westend Correctional Center
Confirmed Asbestos Containing Materials**







<u>Building</u>	<u>Room</u>	<u>NA #</u>	<u>Type</u>	<u>Material Description</u>	<u>Size</u>	<u>Cond</u>	<u>Friable</u>	<u>Asb 1</u>	<u>Asb 2</u>	<u>Asb 3</u>
Wood Building	Comm work prog offices	076	FT	9" white w/black & pink streaks	650 SF	G	N	Chry		3
		076A	FTH	Mastic for floor tile 076	650 SF	G	N	Chry		10
		075	FT	9" gray w/white streaks	750 SF	G	N	Chry		3
	Dressing Rm./Therapy4	075A	FTH	Mastic for floor tile 075	750 SF	G	N	Chry		10
		077	FT	9" white w/multi-colored streaks	5,400 SF	G	N	Chry		6
	Gymnasium	077A	FTH	Mastic for floor tile 077	5,400 SF	G	N	Chry		12
		079	FT	9" gold/brown/white streaks	300 SF	G	N	Chry		4
	X-Ray/Copy Room									



Graphic Scale



Key:


-  Flooring Only
-  Mastic Only
-  Flooring & Mastic
-  Thermal Insulation
-  Ceiling Tile
-  Surfacing Material

Project: NC Department of Correction OSHA Asbestos Survey Umstead - Admin. Building -- 1st Floor		Project No: 95120
Sheet Title: Location of Asbestos Materials		Sheet No: 4255-01-1A
Drawn By: BLB	Brumbaugh-Herrick, inc. 3861 Monroe Street Toledo, OH 43606 (419) 475-1253	
Checked:	Date: 6/08/96	

Graphic Scale



0 5 15 50 feet



Key:

-  Flooring Only
-  Mastic Only
-  Flooring & Mastic

-  Thermal Insulation
-  Ceiling Tile
-  Surfacing Material

Project: NC Department of Correction OSHA Asbestos Survey
Umstead - Admin. Building - 2nd Floor

Sheet Title: Location of Asbestos Materials

Drawn By: BLB

Checked:

Date: 6/08/96


Brumbaugh-Herrick, Inc.

3861 Monroe Street
Toledo, OH 43606
(419) 475-1253


Project No: 95120

Sheet No: 4255-01-2A

Graphic Scale



Key:

-  Flooring Only
-  Mastic Only
-  Flooring & Mastic
-  Thermal Insulation
-  Ceiling Tile
-  Surfacing Material

Project: NC Department of Correction OSHA Asbestos Survey
Umstead - Staff House "A"

Sheet Title:

Location of Asbestos Materials

Drawn By: BLB

Checked:

Date: 6/09/96


Brumbaugh-Herrick, Inc.

3861 Monroe Street
Toledo, OH 43606
(419) 475-1253







Project No: 95120

Sheet No:

4255-02A




Key:

-  Flooring Only
-  Mastic Only
-  Flooring & Mastic
-  Thermal Insulation
-  Ceiling Tile
-  Surfacing Material

Project: NC Department of Correction OSHA Asbestos Survey Umstead - Staff House "B"	
Sheet Title: Location of Asbestos Materials	
Drawn By: ELB	Brumbaugh-Herrick, Inc. 3861 Monroe Street Toledo, OH 43606 (419) 475-1253
Checked:	
Date: 6/09/96	Project No: 95120 Sheet No: 4255-03A

Graphic Scale



Key:

- Flooring Only
- Mastic Only
- Flooring & Mastic

- Thermal insulation
- Ceiling Tile
- Surfacing Material

Project: NC Department of Correction OSHA Asbestos Survey
Umstead - Maintenance Shop

Sheet Title: Location of Asbestos Materials

Drawn By: BLB

Checked:


Date: 6/08/96

Brumbaugh-Herrick, Inc.







3861 Monroe Street
Toledo, OH 43606
(419) 475-1253

Project No: 95120

Sheet No: 4255-04A



Key:


-  Flooring Only
-  Mastic Only
-  Flooring & Mastic
-  Thermal Insulation
-  Ceiling Tile
-  Surfacing Material

Project: NC Department of Correction OSHA Asbestos Survey Umstead - Wood Building/Gym - 1st Floor		Project No: 95120
Sheet Title: Location of Asbestos Materials		Sheet No: 4255-05-1A
Drawn By: BLB	Brumbaugh-Herrick, Inc.	
Checked:	3861 Monroe Street Toledo, OH 43606 (419) 475-1253	
Date: 6/08/96		







Graphic Scale



0 5 15 50 feet



Key:

-  Flooring Only
-  Mastic Only
-  Flooring & Mastic
-  Thermal insulation
-  Ceiling Tile
-  Surfacing Material

Project: NC Department of Correction OSHA Asbestos Survey
Umstead - "A" Dormitory

Sheet Title: Location of Asbestos Materials

Drawn By: BLB

Checked:

Date: 6/08/96


Brumbaugh-Herrick, Inc.

3861 Monroe Street
Toledo, OH 43606
(419) 475-1253







Project No: 95120

Sheet No: 4255-06A

Graphic
Scale



Key:

-  Flooring Only
-  Mastic Only
-  Flooring & Mastic
-  Thermal Insulation
-  Ceiling Tile
-  Surfacing Material

Project: NC Department of Correction OSHA Asbestos Survey
Umstead -- "B" Dormitory

Sheet Title:

Location of Asbestos Materials

Drawn By: BLB

Checked:

Date: 6/09/96

Brumbaugh-Herrick, Inc.

3861 Monroe Street
Toledo, OH 43606
(419) 475-1253

Project No: 95120

Sheet No: 4255-07A

Asbestos Inspection Survey Report - Umstead Correctional Center

Accreditation of Project Participants

The inspection survey was conducted by Mr. Jeffrey P. Kramer who is licensed as an Asbestos Inspector by the NC Department of Environment, Health and Natural Resources, Asbestos Branch:

Jeffrey P. Kramer - #11351

The laboratory used for the analysis of all bulk samples was EMSL Analytical, Inc. of Greensboro, NC. EMSL is an approved laboratory which is accredited by the NVLAP program (National Voluntary Laboratory Accreditation Program), Certification #2104.

Sampling and Analytical Procedures

Each building was visually inspected for materials suspected to contain asbestos. Bulk sampling of suspected ACBM was based on appearance, texture and location of the material, and any material suspected to contain asbestos was hand-touched during the evaluation to determine its friability. The selection of sampling locations was random throughout each homogeneous area of material. Three samples were collected for most homogeneous areas although five or seven samples may have been necessary for surfacing, sprayed-on or trowelled-on materials depending on the quantity of the material. Each sample was individually collected, bagged and labeled. All bulk samples were analyzed utilizing current EPA methods for Polarized Light Microscopy (PLM) by an approved Laboratory which is accredited by the NVLAP program (National Voluntary Laboratory Accreditation Program). As noted in the RFP, analysis in any given homogeneous area was discontinued when a positive result for asbestos was obtained. For quality control purposes five percent of the bulk samples were "split" and sent to a second accredited laboratory for analysis to ensure the quality of the analytical results.

Asbestos Inspection Survey Report - Umstead Correctional Center

Discussion

Each of the pre-1981 buildings at this facility was visually inspected for any material suspected to contain asbestos. Accessible areas included ceilings, walls, floors, surfaces above suspended ceilings, thermal pipe and boiler insulation, ductwork, air plenums and heating and air handling units. The following categories of building materials were considered to be suspect materials:

- floor tile
- floor tile mastic (separate from floor tile)
- linoleum
- linoleum backing (separate from linoleum)
- thermal insulation - boiler lagging
 - pipe wrap
 - tank insulation
 - mudded fittings
 - jacketing
- fireproofing on structural steel
- transite (asbestos cement paneling)
- acoustical plaster
- hard plaster
- "popcorn" ceiling coatings / decorative surfacings
- wallboard / sheet rock system
- ceiling tile
- gaskets

During the inspection each suspect material was identified by homogeneous area, type of material, location, estimated quantity of material and the condition of the material. Each building, room or area suspected to contain ACM has been recorded in the table which can be found as an appendix to this report.

Asbestos containing pipe insulation was commonly used during the era when many of the buildings at this facility were constructed. Some areas of the buildings may have piping between the walls or in other locations that were inaccessible during the survey. No destructive actions were taken to search for such inaccessible materials during this survey.

Asbestos Inspection Survey Report - Umstead Correctional Center

The following building at the Umstead facility had suspect ACM's, were sampled, and the analytical results were negative for asbestos:

Warehouse

**Unstead Correctional Center
All Suspect Asbestos Containing Materials**

Building	Room	HA #	Type	Material Description	Size	Sp. #	ACM	
A Dorm	Basement/Crawlspace	0318	MAG	Magnesia insulation on pipes	600 LF	082, 083, 084	Y	
		027	CT	1x1 white w/holes	3,400 SF	065, 066, 067	N	
	Lobby	026	FT	12" beige speckled	3,400 SF	062, 063, 064	Y	
		026A	FTH	Mastic for floor tile 026	3,400 SF	062A, 063A, 064A	Y	
	A Staff House	closets	028	MAG	Magnesia insul on pipes	300 LF	068, 069, 070	Y
			029	MUD	Mudded fittings on pipe insul	75 EA	071, 072, 073	N
		Through out	030	HP	Hard Plaster	4,200 SF	074, 075, 076	N
			034	FT	9" green w/yellow streaks	950 SF	092, 093, 094	Y
		Various	034A	FTH	Mastic for floor tile 034	950 SF	092A, 093A, 094A	Y
			035	MB	Hallboard/Sheet Rock	10,000 SF	095, 096, 097	N
A Staff House/Boiler Rm		Boiler Room	032	FT	9" brown w/yellow streaks	690 SF	086, 087, 088	Y
			032A	FTH	Mastic for floor tile 032	690 SF	086A, 087A, 088A	Y
		Boiler Room	033	FT	9" black w/yellow streaks	530 SF	089, 090, 091	Y
			033A	FTH	Mastic for floor tile 033	530 SF	089A, 090A, 091A	Y
	Dining Patch	036	FT	9" gray w/streaks	280 SF	098, 099, 100	Y	
		036A	FTH	Mastic for floor tile 036	280 SF	098A, 099A, 100A	Y	
	Administration	Boiler Room	037	FT	9" tan w/dark streaks	140 SF	101, 102, 103	Y
			037A	FTH	Mastic for floor tile 037	140 SF	101A, 102A, 103A	Y
		Boiler Room	038	FT	9" brown/yellow streaked	360 SF	104, 105, 106	Y
			038A	FTH	Mastic for floor tile 038	360 SF	104A, 105A, 106A	Y
Dining Patch		039	FT	12" beige speckled	100 SF	107, 108, 109	N	
		039A	FTH	Mastic for floor tile 039	100 SF	107A, 108A, 109A	Y	
Boiler Room		040	LN	brown/gold block pattern linoleum	260 SF	110, 111, 112	Y	
		041	CT	1x1 white w/holes	280 SF	113, 114, 115	N	
Boiler Room		042	FT	9" brick red w/tan streaks	200 SF	116, 117, 118	Y	
		042A	FTH	Mastic for floor tile 042	200 SF	116A, 117A, 118A	Y	
Boiler Room	043	FT	9" gray w/multi-colored streaks	420 SF	119, 120, 121	Y		
	043A	FTH	Mastic for floor tile 043	420 SF	119A, 120A, 121A	Y		
Boiler Room	044	LP	Layered paper pipe insulation	75 LF	122, 123, 124	Y		
	045	MUD	Mud insul on foamlglass insulation	10 EA	125, 126, 127	N		
Boiler Room	008	MAG	Mag insulation on steam lines	350 LF	012, 013, 014	Y		
	009	MUD	Mudded fittings on steam lines	75 EA	015, 016, 017	N		
Dining Patch	010	MAG	Mag insulation on hot H2O tank	100 SF	018, 019, 020	N		
	007	FT	9" blue w/green streaks	40 SF	009, 010, 011	Y		

**Winstead Correctional Center
All Suspect Asbestos Containing Materials**

Building	Room	IA #	Type	Material Description	Size	Spl #	ACH		
Administration	Dining Patch	007A	FTH	Mastic for floor tile 007	40 SF	009A, 010A, 011A	Y		
	Dining, 2nd Flr. Hall	006	CT	2x2 large fissures w/holes	2,125 SF	006, 007, 008	H		
	Dining, Stairwells	004	FT	9" beige w/brown flecks	1,325 SF	999, 001, 002	Y		
	Front offices		004A	FTH	Mastic for floor tile 004	1,325 SF	999A, 001A, 002A	H	
		Kitchen	002	CT	1x1 white w/holes	480 SF	993, 994, 995	H	
		Nurse's Office	005	CT	1x1 large fissured	650 SF	003, 004, 005	H	
	Throughout		003	CT	2x2 smooth	360 SF	996, 997, 998	H	
			011	MAG	Magnesia pipe insulation	2,000 LF	021, 022, 023	Y	
	Throughout 1st floor		012	LP	Layered paper pipe insulation	700 LF	024	N	
			015	HP	Hard Plaster	15,000 SF	031, 032, 033	H	
			016	MUD	Mud fittings on steam/water lines	400 EA	034, 035, 036	Y	
			001	FT	12" beige speckled	6,000 SF	990, 991, 992	Y	
			001A	FTH	Mastic for floor tile 001	6,000 SF	990A, 991A, 992A	Y	
			013	FT	9" brown w/streaks	3,300 SF	025, 026, 027	Y	
			013A	FTH	Mastic for floor tile 013	3,300 SF	025A, 026A, 027A	Y	
			014	CT	1x1 large fissures	3,200 SF	028, 029, 030	H	
		Lobby		016	CT	1x1 white w/holes	300 SF	040, 041, 042	H
			Throughout	017	FT	12" beige speckled	4,000 SF	037, 038, 039	Y
B Dorm	Throughout	017A	FTH	Mastic for floor tile 017	4,000 SF	037A, 038A, 039A	Y		
		019	MAG	Mag insulation on steam pipes	900 LF	043, 044, 045	Y		
		020	MUD	Mud fittings on hot H2O lines	150 EA	046, 047, 048	Y		
	Throughout dorms	022	LP	Layered paper pipe insulation	300 LF	052	Y		
		023	HP	Hard Plaster walls	8,000 SF	053, 054, 055	N		
	B Staff House	Throughout	024	HP	Hard Plaster ceiling	3,400 SF	056, 057, 058	H	
			025	HP	Brown coat ceiling	3,400 SF	059, 060, 061	N	
		Throughout	021	CT	2x1 w/holes	3,100 SF	049, 050, 051	H	
			065	MB	Wallboard/Sheet Rock	10,000 SF	179, 180, 181	H	
		Various Rooms	055	FT	9" green w/yellow streaks	520 SF	149, 150, 151	N	
			055A	FTH	Mastic for floor tile 055	520 SF	149A, 150A, 151A	Y	
			056	FT	9" brown w/multi-colored streaks	630 SF	152, 153, 154	Y	
			056A	FTH	Mastic for floor tile 056	630 SF	152A, 153A, 154A	Y	
			057	FT	9" black w/white streaks	480 SF	155, 156, 157	Y	
			057A	FTH	Mastic for floor tile 057	480 SF	155A, 156A, 157A	Y	
058	FT	9" gray w/light & dark streaks	280 SF	158, 159, 160	Y				

**Unstead Correctional Center
All Suspect Asbestos Containing Materials**

Building	Room	HA #	Type	Material Description	Size	Sp. #	ACH		
B Staff House	Various Rooms	050A	FTM	Mastic for floor tile 058	200 SF	150A, 159A, 160A	Y		
		059	FT	9" brown w/yellow streaks	280 SF	161, 162, 163	Y		
		059A	FTM	Mastic for floor tile 059	280 SF	161A, 162A, 163A	Y		
		060	FT	12" white w/black streaks	700 SF	164, 165, 166	Y		
		060A	FTM	Mastic for floor tile 060	700 SF	164A, 165A, 166A	Y		
		061	CI	1x1 w/holes	260 SF	167, 168, 169	N		
		062	FT	9" gray w/multi-colored streaks	630 SF	170, 171, 172	Y		
		062A	FTM	Mastic for floor tile 062	630 SF	170A, 171A, 172A	Y		
		063	FT	9" beige w/dark streaks	470 SF	173, 174, 175	Y		
		063A	FTM	Mastic for floor tile 063	470 SF	173A, 174A, 175A	Y		
		064	FT	9" red w/light streaks	130 SF	176, 177, 178	Y		
		064A	FTM	Mastic for floor tile 064	130 SF	176A, 177A, 178A	Y		
		B Staff House/Boiler Rm	Boiler Room	066	LP	Layered paper pipe insulation	55 LF	182	Y
				067	MUD	Mudded' insul on FG pipe insul	10 EA	183, 184, 185	Y
Duplex	Furnace Rooms	052	TP	Transite Panels	380 SF	144	Y		
		053	JF	Jacket on FG pipe insul	20 LF	145	H		
Maintenance Bldg	Throughout	054	MUD	Mud fittings on FG pipe insul	9 LF	146, 147, 148	N		
		050	FT	12" white w/beige streaks	2,100 SF	138, 139, 140	Y		
		050A	FTM	Mastic for floor tile 050	2,100 SF	138A, 139A, 140A	Y		
		051	NB	Wallboard/Sheet Rock	5,000 SF	141, 142, 143	N		
		069	FT	12" gold w/brown streaks	530 SF	189, 190, 191	Y		
		069A	FTM	Mastic for floor tile 069	530 SF	189A, 190A, 191A	Y		
		068	MUD	Mudded insul on FG pipe insul	22 EA	186, 187, 188	N		
		070	NB	Wallboard/Sheet Rock	2,500 SF	192, 193, 194	N		
		046	LN	White w/black & gray flecks	55 SF	128, 129, 130	H		
		046A	LNB	Backing for linoleum 046	55 SF	128A, 129A, 130A	N		
Supt's Residence	Furnace Room Kitchen/Back Porch	048	TP	Transite Panels	190 SF	134	Y		
		047	LN	Green linoleum	280 SF	131, 132, 133	Y		
		047A	LNB	Backing for linoleum 047	280 SF	131A, 132A, 133A	H		
		049	NB	Wallboard/Sheet Rock	4,000 SF	135, 136, 137	N		
		031	SF	Sprayed-on fireproofing	1,330 SF	077, 078, 079	H		
		071	JF	Jacket on FG pipe insul, old	25 LF	195, 196, 197	N		
		072	MUD	Mud fittings on old FG pipe insul	100 EA	198, 199, 200	Y		
Warehouse Hood Building	Bowling/Variou Offices/Class	074	FT	9" beige w/brown streaks	2,750 SF	204, 205, 206	Y		


**Wasland Correctional Center
All Suspect Asbestos Containing Materials**

<u>Building</u>	<u>Room</u>	<u>HA #</u>	<u>Type</u>	<u>Material Description</u>	<u>Size</u>	<u>Spl #</u>	<u>ACM</u>
Wood Building	Bowling/Various Offices/Class Comm work prog offices	074A	FTH	Mastic for floor tile 074	2,750 SF	204A, 205A, 206A	Y
		076	FT	9" white w/black & pink streaks	650 SF	210, 211, 212	Y
	Dressing Rm./Therapy4	076A	FTH	Mastic for floor tile 076	650 SF	210A, 211A, 212A	Y
		075	FT	9" gray w/white streaks	750 SF	207, 208, 209	Y
	Gymnasium	075A	FTH	Mastic for floor tile 075	750 SF	207A, 208A, 209A	Y
		077	FT	9" white w/multi-colored streaks	5,400 SF	213, 214, 215	Y
	Hallways, Various Rm Waiting Rm/Dental Clinic	077A	FTH	Mastic for floor tile 077	5,400 SF	213A, 214A, 215A	Y
		073	CT	1x1 white w/large fissures, small holes	6,500 SF	201, 202, 203	N
	X-Ray/Copy Room	078	FT	12" white w/gray flecks	475 SF	216, 217, 218	N
		078A	FTH	Mastic for floor tile 078	475 SF	216A, 217A, 218A	N
		079	FT	9" gold/brown/white streaks	300 SF	219, 220, 221	Y
		079A	FTH	Mastic for floor tile 079	300 SF	219A, 220A, 221A	N

TYPE OF MATERIAL CODES

N.C. DEPARTMENT OF CORRECTION

<u>CODE</u>	<u>DESCRIPTION</u>
AC	AIRCELL THERMAL INSULATION
CT	CEILING TILE
DS	DECORATIVE CEILING MATERIAL
FD	FIRE DOOR
FT	FLOOR TILE
FTM	FLOOR TILE MASTIC
GA	GASKET
PL	HARD PLASTER (WALL OR CEILING)
JF	JACKET ON FIBERGLASS THERMAL INSULATION
LN	LINOLEUM FLOORING
LNB	LINOLEUM BACKING
MAG	MAGNESIA OR CALCIFORM THERMAL INSULATION
MJP	MUDDERED JOINT PACKING
MW	MINERAL WOOL, MINERAL FIBER, ETC
PI	OTHER PIPE INSULATION
SF	SPRAYED-ON FIREPROOFING
TP	ASBESTOS CEMENT PANELING
WB	WALLBOARD/SHEETROCK/JOINT COMPOUND




Project: NC Department of Correction OSHA Asbestos Survey Umstead - Admin, Building - 1st Floor		Project No: 95120
Sheet Title: Asbestos Sample Locations		Sheet No: 4255-01-1S
Drawn By: BLE	Brumbaugh-Herrick, Inc.	
Checked:	3861 Monroe Street Toledo, OH 43606 (419) 473-1253	
Date: 6/08/96		

Graphic
Scale




0 5 15 50 feet



Project: NC Department of Correction OSHA Asbestos Survey Umstead - Admin. Building - 2nd Floor	
Sheet Title: Asbestos Sample Locations	
Drawn By: BLB	Project No: 95120
Checked:	Sheet No: 4255-01-25
Date: 6/08/96	Brumbaugh-Herrick, Inc. 3861 Monroe Street Toledo, OH 43606 (419) 475-1253

Graphic
Scale



Project: NC Department of Correction OSHA Asbestos Survey
Umstead - Staff House "A"

Sheet Title: Asbestos Sample Locations

Drawn By: BLB

Checked:

Date: 6/09/96


Brumbaugh-Herrick, Inc.

3551 Monroe Street
Toledo, OH 43606
(419) 475-1253

Project No: 95120

Sheet No: 4255-02S

Graphic
Scale



Project: NC Department of Correction OSHA Asbestos Survey
Umstead - Staff House "B"

Sheet Title: Asbestos Sample Locations

Drawn by: BLB

Checked:

Date: 6/09/90


Brumbaugh-Herrick, Inc.

3861 Monroe Street
Tolledo, OH 43606
(419) 475-1253

Project No: 95120

Sheet No: 4255-035

Graphic
Scale



Project: NC Department of Correction OSHA Asbestos Survey
Umstead - Maintenance Shop

Sheet Title: Asbestos Sample Locations

Drawn By: BLB

Checked:

Date: 6/08/96

Brumbaugh-Herrick, Inc.


3861 Monroe Street
Toledo, OH 43606
(419) 475-1253

Project No: 95120

Sheet No: 4255-04S


Graphic Scale

0 5 15 50 feet




Project: NC Department of Correction OSHA Asbestos Survey Umstead - Wood Building/Gym - 1st Floor	
Sheet Title: Asbestos Sample Locations	
Drawn By: BLB	Project No: 95120
Checked:	Sheet No: 4255-05-1S
Date: 6/08/98	Brumbaugh-Herrick, Inc. 3861 Monroe Street Toledo, OH 43606 (419) 475-1253

Graphic
Scale



Project: NC Department of Correction OSHA Asbestos Survey Umstead - "A" Dormitory	
Sheet Title: Asbestos Sample Locations	
Drawn By: BLB	Project No: 95120
Checked:	Sheet No: 4255-06S
Date: 6/08/96	
Brumbaugh-Herrick, Inc. 3861 Monroe Street Toledo, OH 43606 (419) 475-1253	

Graphic
Scale



Project: NC Department of Correction OSHA Asbestos Survey Umstead - "B" Dormitory	
Sheet Title: Asbestos Sample Locations	
Drawn By: BLB	Project No: 95120
Checked:	Sheet No: 4255-07S
Date: 6/09/98	
Brumbaugh-Herrick, Inc. 3881 Monroe Street Toledo, OH 43606 (419) 475-1253	

Worcester, NJ
609-488-4300

Piscataway, NJ
908-981-0550

Carle Place, NY
516-997-7251

Manassas, NY
212-290-0152

Melbourne, FL
407-726-5233

Ann Arbor, MI
313-488-0810

San Mateo, CA
415-870-5401

Smyrna, GA
404-333-8066



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS			
				%	TYPE	%	FIBROUS	%	NONFIBROUS
L990	Tile	Beige Non-Fibrous Homogeneous	Crushed/Dissolved	2%	Chrysotile	1%	Cellulose	97%	Other
L990A	Mastic	Black Non-Fibrous Homogeneous	Teased	5%	Chrysotile	2%	Cellulose	93%	Other
L993	Paint	White Non-Fibrous Homogeneous	Ashed/Crushed		None Detected			100%	Other
L993A	Ceiling tile	Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose		
L994	Ceiling tile	Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose		
L995	Paint	White Non-Fibrous Homogeneous	Ashed/Crushed		None Detected			100%	Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow

David Buetow
Analyst

R.K. Mahoney

Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westmont, NJ
609-962-4300

Piscataway, NJ
908-981-0550

Carle Place, NY
516-887-7251

Manhattan, NY
212-290-0052

Melbourne, FL
407-735-5223

Ann Arbor, MI
313-969-6810

San Mateo, CA
415-870-6401

Sayron, CA
484-333-8066



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
95A	Ceiling tile	Brown Fibrous Homogeneous	Teased	None Detected		100% Cellulose	
96		Orange Fibrous Homogeneous	Teased	None Detected		1% Cellulose 99% Min. Wool	
97	Paint	White Non-Fibrous Homogeneous	Ashed/Crushed	None Detected		2% Wollastonite	98% Other
97A	Orange fibers	Orange Fibrous Homogeneous	Teased	None Detected		100% Min. Wool	
98		Orange Fibrous Homogeneous	Teased	None Detected		100% Min. Wool	
99	Tile	Beige Non-Fibrous Homogeneous	Crushed/Dissolved	4% Chrysotile			96% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. No. "# of Layers" refers to number of separable subsamples. Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R. K. Maloney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and vapes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westport, NJ
609-838-1806

Placataway, NJ
908-981-0530

Carle Place, NY
516-937-7251

Manhattan, NY
212-290-0062

Melbourne, FL
407-725-5823

Ann Arbor, MI
313-663-6810

San Mateo, CA
415-570-6601

Smyrna, GA
404-333-6986



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility


SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS
104A	Ceiling tile	Grey Fibrous Homogeneous	Crushed	None Detected		97% Min. Wool	3% Other
105	Paint	Grey Fibrous Homogeneous	Crushed	None Detected		98% Min. Wool	2% Other
105A	Ceiling tile	Grey Fibrous Homogeneous	Crushed	None Detected		98% Min. Wool	2% Other
106	Paint	White Non-Fibrous Homogeneous	Ashed/Crushed	None Detected		3% Min. Wool	97% Other
106A	Ceiling tile	Grey Fibrous Homogeneous	Crushed	None Detected		80% Min. Wool 35% Cellulose	5% Perlite
107	Paint	White Non-Fibrous Homogeneous	Ashed/Crushed	None Detected		3% Min. Wool	97% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. No. "# of Layers" refers to number of separable subsamples. Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R. K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.



Herrick Engineering Inc.
 1705 Chatsworth Lane
 Raleigh, NC 27614

Friday, April 26, 1996
 Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS
M007A	Ceiling tile	Grey Fibrous Homogeneous	Crushed		None Detected	60% Min. Wool 35% Cellulose	5% Perlite
M008	Paint	White Non-Fibrous Homogeneous	Ashed/Crushed		None Detected	2% Min. Wool	98% Other
M008A	Ceiling tile	Grey Fibrous Homogeneous	Crushed		None Detected	60% Min. Wool 30% Cellulose	10% Perlite
M009	Tile	Blue/Green Non-Fibrous Homogeneous	Crushed/Dissolved		2% Chrysotile		98% Other
M009A	Mastic	Brown Non-Fibrous Homogeneous	Teased		None Detected	5% Cellulose	95% Other
M010A	Mastic	Brown/Black Non-Fibrous Homogeneous	Teased		None Detected	5% Cellulose	95% Other


Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow
 David Buetow
 Analyst

R.K. Mahoney
 Laboratory
 Supervisor

Other Approved
 Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westmont, NJ
908-652-4869

Hickory, NJ
908-961-0620

Carle Place, NY
516-947-7351

Manhattan, NY
212-280-0352

Melbourne, FL
407-725-8223

Ann Arbor, MI
313-868-6810

San Mateo, CA
415-670-6401

Smyrna, GA
404-333-6066



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
L999A	Mastic	Brown Non-Fibrous Homogeneous	Teased	None Detected		2% Cellulose	98% Other
M001A	Mastic	Brown/Black Non-Fibrous Homogeneous	Teased	None Detected		5% Cellulose < 1% Min. Wool	95% Other
M002A	Mastic	Brown Non-Fibrous Homogeneous	Teased	None Detected		2% Cellulose	98% Other
M003	Paint	Beige Non-Fibrous Homogeneous	Ashed/Crushed	None Detected		2% Min. Wool	98% Other
M003A	Ceiling tile	Grey Fibrous Homogeneous	Crushed	None Detected		95% Min. Wool	5% Other
M004	Paint	Beige Non-Fibrous Homogeneous	Ashed/Crushed	None Detected		2% Min. Wool	98% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R. K. Maloney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westmont, NJ
609-453-4800

Macataway, NJ
908-981-9589

Clark Place, NY
516-997-7251

Manhattan, NY
212-290-0053

Melbourne, FL
407-726-6223

Ann Arbor, MI
313-868-4810

San Mateo, CA
415-570-5401

Smyrna, GA
404-333-6086



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility


SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
111A	Mastic	Brown Non-Fibrous Homogeneous	Teased		None Detected	5% Cellulose	95% Other
111B	Black mastic	Black Non-Fibrous Homogeneous	Teased		5% Chrysotile		95% Other
112		White Fibrous Homogeneous	Teased/Crushed		30% Amosite	2% Cellulose	68% Other
115		Grey Fibrous Homogeneous	Crushed		None Detected	35% Min. Wool	65% Other
116		Grey Fibrous Homogeneous	Crushed		None Detected	40% Min. Wool	60% Other
117		Grey Fibrous Homogeneous	Crushed		None Detected	40% Min. Wool	60% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. "o. # of Layers" refers to number of separable subsamples.
Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R. K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westmont, NJ
609-838-4900

Piscataway, NJ
908-981-0650

Carle Place, NY
516-937-7251

Manhasset, NY
212-230-0052

Melbourne, FL
407-725-6223

Ann Arbor, MI
313-468-6810

San Mateo, CA
415-670-5481

Smyrna, GA
404-333-6086



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS
M018		Gray Fibrous Homogeneous	Teased	40%	Chrysotile		60% Other
M021		Pink Fibrous Homogeneous	Teased/Crushed	10%	Chrysotile 20% Amosite		70% Other
M024	Brown paper layer	Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose
M024A	Black paper layer	Black Fibrous Homogeneous	Teased		None Detected	98%	Cellulose 2% Other
M025	Tile	Brown Non-Fibrous Homogeneous	Crushed/Dissolved	10%	Chrysotile		90% Other
M025A	Mastic	Black Non-Fibrous Homogeneous	Teased	10%	Chrysotile	2%	Cellulose 88% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Maloney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westport, NJ
908-632-4800

Parsippany, NJ
908-861-0550

Carle Place, NY
516-997-7251

Manhasset, NY
212-290-0652

Melbourne, FL
407-725-6223

Ann Arbor, MI
313-668-6310

San Mateo, CA
415-670-6401

Smyrna, GA
404-333-6966



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS
128	Paint	White Non-Fibrous Homogeneous	Ashed/Crushed		None Detected		100% Other
128A	Ceiling tile	Grey Fibrous Homogeneous	Crushed		None Detected	98% Min. Wool	2% Other
129	Paint	White Non-Fibrous Homogeneous	Ashed/Crushed		None Detected		100% Other
129A	Ceiling tile	Grey Fibrous Homogeneous	Crushed		None Detected	98% Min. Wool	2% Other
130	Paint	White Non-Fibrous Homogeneous	Ashed/Crushed		None Detected	1% Min. Wool	99% Other
130A	Ceiling tile	Grey Homogeneous	Crushed		None Detected	98% Min. Wool < 1% Cellulose	2% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. " # of Layers" refers to number of separable subsamples.
Note: Sample- M107 (A) is at the end of report.

David H. Buelow
David Buelow
Analyst

R. K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westmont, NJ
908-858-4800

Placetaway, NJ
908-961-0550

Carle Place, NY
516-977-7251

Manhattan, NY
212-290-0652

Melbourne, FL
407-726-5223

Ann Arbor, MI
313-968-6310

San Mateo, CA
415-678-5401

Smyrna, GA
404-333-4086



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
M031	Paint	Yellow/Green Non-Fibrous Homogeneous	Ashed/Crushed	None Detected			100% Other
M031A	Plaster	White Non-Fibrous Homogeneous	Crushed	None Detected	< 1% Cellulose		100% Other
M032	Paint	Yellow Non-Fibrous Homogeneous	Ashed/Crushed	None Detected			100% Other
M032A	Gray layer	Grey Non-Fibrous Homogeneous	Crushed	None Detected	2% Min. Wool		98% Other
M032B	White layer	White Non-Fibrous Homogeneous	Crushed	None Detected	< 1% Cellulose		100% Other
M033	Paint	Yellow/Green Non-Fibrous Homogeneous	Ashed/Crushed	None Detected			100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.
Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R. H. Maloney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westport, NJ
909-852-4300

Piscataway, NJ
908-981-0550

Carle Place, NY
516-987-7251

Manhattan, NY
212-290-0062

Melbourne, FL
407-725-9223

Ann Arbor, MI
313-669-6810

San Mateo, CA
415-870-6481

Smayna, GA
404-333-8066



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS		
				%	TYPE	%	FIBROUS	%
133A	Gray layer	Grey Non-Fibrous Homogeneous	Crushed		None Detected			50% Quartz 50% Other
133B	White layer	White Non-Fibrous Homogeneous	Crushed		None Detected	< 1%	Cellulose	100% Other
134		Grey Fibrous Homogeneous	Crushed	60%	Chrysotile	20%	Min. Wool	20% Other
137	Tile	Beige Non-Fibrous Homogeneous	Crushed/Dissolved	3%	Chrysotile			97% Other
137A	Mastic	Black Non-Fibrous Homogeneous	Teased/Crushed	15%	Chrysotile	10%	Cellulose	75% Other
140		Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose	

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. "No. of Layers" refers to number of separable subsamples. Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R. K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westmont, NJ
609-523-4200

Plainsboro, NJ
908-981-0550

Carle Place, NY
516-997-7251

Manhastan, NY
212-230-0082

Melbourne, FL
407-725-5223

Ann Arbor, MI
313-668-6810

San Mateo, CA
415-570-6401

Smyrna, GA
404-333-6068



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS		
				%	TYPE	%	FIBROUS	%
M041		Brown Fibrous Homogeneous	Teased		None Detected		100% Cellulose	
M042		Brown Fibrous Homogeneous	Teased		None Detected		100% Cellulose	
M043		White Fibrous Homogeneous	Teased		25% Chrysotile 10% Amosite			65% Other
M046		Grey Fibrous Homogeneous	Crushed		None Detected		60% Min. Wool	40% Other
M047		Grey Fibrous Homogeneous	Crushed		None Detected		60% Min. Wool	40% Other
M048		Grey Fibrous Homogeneous	Teased		60% Chrysotile		5% Min. Wool	35% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westmont, NJ
609-662-1200

Hickory, NJ
908-981-0550

Carle Place, NY
516-987-7251

Manhattan, NY
212-290-0052

Melbourne, FL
407-725-5223

Auburn, MI
313-969-8810

San Mateo, CA
415-670-5401

Smyrna, GA
404-333-6926



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
149	Paint	Beige Non-Fibrous Homogeneous	Ashed/Crushed		None Detected		100% Other
149A	Ceiling tile	Grey Fibrous Homogeneous	Teased		None Detected	70% Min. Wool 30% Cellulose	
150	Paint	Beige Non-Fibrous Homogeneous	Ashed/Crushed		None Detected		100% Other
150A	Ceiling tile	Grey Fibrous Homogeneous	Teased		None Detected	70% Min. Wool 30% Hair	
151	Paint	Beige Non-Fibrous Homogeneous	Ashed/Crushed		None Detected		100% Other
151A	Ceiling tile	Grey Fibrous Homogeneous	Teased		None Detected	70% Min. Wool 30% Cellulose	

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. # of Layers refers to number of separable subsamples.
Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westport, NJ
908-933-4800

Placataway, NJ
908-981-0550

Carle Place, NY
516-937-7251

Manassas, NY
212-230-0052

Melbourne, FL
407-725-5222

Ann Arbor, MI
313-668-6810

San Mateo, CA
415-870-6401

Smyrna, GA
404-333-8066



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
M052	Brown paper	Brown Fibrous Homogeneous	Teased		None Detected	100% Cellulose	
M052A	Black paper	Black Fibrous Homogeneous	Teased		None Detected	98% Cellulose	2% Other
M053		White Non-Fibrous Homogeneous	Crushed		None Detected	< 1% Cellulose < 1% Min. Wool	100% Other
M054		White Non-Fibrous Homogeneous	Crushed		None Detected	< 1% Min. Wool	100% Other
M055		White Non-Fibrous Homogeneous	Crushed		None Detected	< 1% Cellulose	100% Other
M056	Paint	Beige/Green Non-Fibrous Homogeneous	Ashed/Crushed		None Detected		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R. L. Maloney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westport, NJ
609-662-2200

Placetown, NJ
908-961-0560

Carle Place, NY
516-397-7351

Manhattan, NY
212-290-0082

Melbourne, FL
407-725-6223

Ann Arbor, MI
313-663-6810

San Mateo, CA
415-670-5401

Smyrna, GA
404-333-6066



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
156A	Plaster	White Non-Fibrous Homogeneous	Crushed		None Detected	1% Min. Wool < 1% Cellulose	20% Perlite 79% Other
157	Paint	Beige/Green Non-Fibrous Homogeneous	Ashed/Crushed		None Detected		100% Other
157A	Plaster	White Non-Fibrous Homogeneous	Crushed		None Detected		30% Quartz 70% Other
158	Paint	Beige/Green Non-Fibrous Homogeneous	Ashed/Crushed		None Detected		100% Other
158A	Plaster	White Non-Fibrous Homogeneous	Crushed		None Detected		20% Quartz 80% Other
159		Brown Non-Fibrous Homogeneous	Crushed		None Detected		80% Quartz 20% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. o. "# of Layers" refers to number of separable subsamples.
Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Maloney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westmont, NJ
908-838-6100

Placataway, NJ
908-581-0500

Carle Place, NY
516-937-7251

Manhattan, NY
212-290-0052

Melbourne, FL
407-725-5223

Ann Arbor, MI
313-963-6310

San Mateo, CA
415-670-6401

Smyrna, GA
404-333-4066



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS		
				%	TYPE	%	FIBROUS	%
M060		Brown Non-Fibrous Homogeneous	Crushed		None Detected	< 1%	Min. Wool	80% Quartz 20% Other
M061		Brown Non-Fibrous Homogeneous	Crushed		None Detected	< 1%	Min. Wool	80% Quartz 20% Other
M062	Tile	Beige Non-Fibrous Homogeneous	Crushed/Dissolved	2%	Chrysotile	< 1%	Other	98% Other
M062A	Mastic	Black Non-Fibrous Homogeneous	Teased	15%	Chrysotile	2%	Cellulose	83% Other
M065		Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose	
M066		Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose	

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Mahony
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westport, NJ
609-438-4800

Piscataway, NJ
908-961-0550

Carle Place, NY
516-997-7251

Manhasset, NY
516-290-0052

Melbourne, FL
407-725-6223

Ann Arbor, MI
313-668-6310

San Mateo, CA
415-670-5461

Smyrna, GA
404-333-6064



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS		
				%	TYPE	%	FIBROUS	%
167		Brown Fibrous Homogeneous	Teased		None Detected		100% Cellulose	
168		White Fibrous Homogeneous	Teased		20% Chrysotile 15% Amosite			65% Other
171		Grey Fibrous Homogeneous	Crushed		None Detected		70% Min. Wool < 1% Cellulose	30% Other
172		Grey Fibrous Homogeneous	Crushed		None Detected		75% Min. Wool	25% Other
173		Grey Fibrous Homogeneous	Crushed		None Detected		75% Min. Wool < 1% Cellulose	25% Other
174		Grey Non-Fibrous Homogeneous	Crushed		None Detected			60% Quartz 40% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. The "# of Layers" refers to number of separable subsamples. Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Maloney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Worcester, MA
608-898-4300

Piscataway, NJ
908-961-8650

Carle Place, NY
516-987-7251

Manhattan, NY
212-398-0062

Melbourne, FL
407-726-8223

Ann Arbor, MI
313-968-6810

San Mateo, CA
415-678-6403

Smyrna, GA
404-333-8088



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS		
				%	TYPE	%	FIBROUS	%
M075		Grey Non-Fibrous Homogeneous	Crushed		None Detected	1%	Cellulose	70% Quartz 29% Other
M076		Grey Non-Fibrous Homogeneous	Crushed		None Detected			70% Quartz 30% Other
M077		Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose	
M078		Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose	
M079		Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose	
M080		Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose	

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.





Herrick Engineering Inc.
 1705 Chatsworth Lane
 Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
181		Brown Fibrous Homogeneous	Teased		None Detected	100% Cellulose	
182		Pink Fibrous Homogeneous	Teased	5% Chrysotile 25% Amosite			70% Other
186	Tile	Brown Non-Fibrous Homogeneous	Crushed/Dissolved	15% Chrysotile			86% Other
186A	Mastic	Black Non-Fibrous Homogeneous	Teased	10% Chrysotile		2% Cellulose	88% Other
189	Tile	Black Non-Fibrous Homogeneous	Crushed/Dissolved	10% Chrysotile			90% Other
189A	Mastic	Black Non-Fibrous Homogeneous	Teased	15% Chrysotile		2% Cellulose	83% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. So, "# of Layers" refers to number of separable subsamples.
 Note: Sample- M107 (A) is at the end of report.

David H. Buetow
 David Buetow
 Analyst

R. K. Maloney
 Laboratory
 Supervisor

Other Approved
 Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westport, NJ
609-852-1808

Placetown, NJ
908-981-0560

Carle Place, NY
516-937-7251

Manhattan, NY
212-290-0062

Melbourne, FL
407-726-5223

Ann Arbor, MI
313-668-6810

San Mateo, CA
415-678-5401

Smyrna, GA
404-333-8088



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS			
				%	TYPE	%	FIBROUS	%	NONFIBROUS
M092	Tile	Green Non-Fibrous Homogeneous	Crushed/Dissolved	18%	Chrysotile			82%	Other
M092A	Mastic	Black Non-Fibrous Homogeneous	Teased	5%	Chrysotile	10%	Cellulose 5% Synthetic	80%	Other
M095	Paint	Beige/Blue Non-Fibrous Homogeneous	Ashed/Crushed		None Detected			100%	Other
M095A	Wallboard	Grey Non-Fibrous Homogeneous	Crushed		None Detected	15%	Cellulose	85%	Other
M096	Paint	Beige/Blue Non-Fibrous Homogeneous	Ashed/Crushed		None Detected	< 1%	Other	100%	Other
M096A	Wallboard	Grey Non-Fibrous Homogeneous	Crushed		None Detected	15%	Cellulose	85%	Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.


Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.



Westwood, NJ
908-333-0200

Placataway, NJ
308-981-0550

Carle Place, NY
516-997-7251

Manhattan, NY
212-290-0052

Melbourne, FL
407-725-6223

Ann Arbor, MI
313-663-6810

San Mateo, CA
415-670-6401

Smyrna, GA
404-333-6068



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS			
				%	TYPE	%	FIBROUS	%	NONFIBROUS
197		Grey Non-Fibrous Homogeneous	Crushed		None Detected	15%	Cellulose	85%	Other
198	Tile	Grey Non-Fibrous Homogeneous	Crushed/Dissolved	12%	Chrysotile			88%	Other
198A	Mastic	Black Non-Fibrous Homogeneous	Teased	10%	Chrysotile	2%	Cellulose	88%	Other
101	Tile	Tan Non-Fibrous Homogeneous	Crushed/Dissolved	8%	Chrysotile			92%	Other
101A	Mastic	Black Non-Fibrous Homogeneous	Teased	5%	Chrysotile	10%	Cellulose	85%	Other
104	Tile	Brown Non-Fibrous Homogeneous	Crushed/Dissolved	8%	Chrysotile			92%	Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. No. "# of Layers" refers to number of separable subsamples.
Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westport, NJ
609-652-4300

Plainville, NJ
908-981-0850

Carle Place, NY
516-967-7251

Manhasset, NY
212-280-0052

Melbourne, FL
407-725-4223

Ann Arbor, MI
313-663-6810

San Mateo, CA
415-670-6401

Savanna, GA
404-333-6088



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS
M104A	Mastic	Black Non-Fibrous Homogeneous	Teased	15%	Chrysotile		85% Other
M107**	Tile	Beige Non-Fibrous Homogeneous	Crushed/Dissolved		None Detected		100% Other
M108	Tile	Beige Non-Fibrous Homogeneous	Crushed/Dissolved		None Detected		100% Other
M109	Tile	Brown/Tan Non-Fibrous Homogeneous	Crushed/Dissolved		None Detected		100% Other
M110		Brown/Tan Other Heterogeneous	Teased	40%	Chrysotile	10% Cellulose	50% Other
M113	Paint	Beige Non-Fibrous Homogeneous	Ashed/Crushed		None Detected		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.
Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.H. Maloney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westmont, NJ
908-558-8808

Florence, NJ
303-981-0660

Carle Place, NY
516-997-7261

Manhasset, NY
212-290-0062

Melbourne, FL
407-725-6223

Ann Arbor, MI
313-488-8810

San Mateo, CA
415-670-5401

Savannah, GA
404-353-6086



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
113A	Ceiling tile	Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose
114	Paint	Beige Non-Fibrous Homogeneous	Ashed/Crushed		None Detected		100% Other
114A	Ceiling tile	Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose
115	Paint	Beige Non-Fibrous Homogeneous	Ashed/Crushed		None Detected		100% Other
115A	Ceiling tile	Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose
116	Tile	Red Non-Fibrous Homogeneous	Crushed/Dissolved		8% Chrysotile		92% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. So, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R. K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.



Worcester, NJ
909-853-4800

Piscataway, NJ
908-981-0550

Carle Place, NY
516-937-7251

Manhattan, NY
212-290-0062

Melbourne, FL
407-725-0223

Ann Arbor, MI
313-668-8810

San Mateo, CA
415-570-5401

Savannah, GA
404-333-8968



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS			
				%	TYPE	%	FIBROUS	%	NONFIBROUS
M116A	Mastic	Black Non-Fibrous Homogeneous	Teased	5%	Chrysotile	5%	Cellulose	90%	Other
M119	Tile	Grey Non-Fibrous Homogeneous	Crushed/Dissolved	8%	Chrysotile			92%	Other
M119A	Mastic	Black Non-Fibrous Homogeneous	Teased	10%	Chrysotile	5%	Cellulose	85%	Other
M122	Gray paper layer	Grey Fibrous Homogeneous	Teased	60%	Chrysotile	30%	Cellulose	10%	Other
M122A	Brown paper layer	Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose		
M123A	Brown paper layer	Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose		

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R. K. Maloney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westport, NJ
609-852-4300

Piscataway, NJ
908-961-0650

Carle Place, NY
516-997-7261

Manhattan, NY
212-290-0052

Melbourne, FL
407-726-5223

Ann Arbor, MI
313-963-6310

San Mateo, CA
415-670-8401

Smyrna, GA
404-333-8066



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS		
				%	TYPE	%	FIBROUS	%
24A	Brown paper layer	Brown Fibrous Homogeneous	Teased		None Detected		100% Cellulose	
24B	White woven mesh	White Fibrous Homogeneous	Teased		None Detected		100% Cellulose	
25		Grey Non-Fibrous Homogeneous	Crushed		None Detected		30% Min. Wool	70% Other
26		Grey Non-Fibrous Homogeneous	Crushed		None Detected		30% Min. Wool	70% Other
127		Grey Non-Fibrous Homogeneous	Crushed		None Detected		30% Min. Wool	70% Other
128	Linoleum	Various Other Heterogeneous	Teased		None Detected		40% Cellulose 20% Synthetic	40% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples. Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westmont, NJ
908-858-6500

Piscataway, NJ
908-981-0800

Carle Place, NY
516-997-7251

Manhasset, NY
212-230-0052

Melbourne, FL
407-725-5223

Ann Arbor, MI
313-668-6810

San Mateo, CA
415-670-5401

Smyrna, GA
404-333-8868



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
M128A	Mastic	Black Non-Fibrous Homogeneous	Teased	None Detected		5% Cellulose	95% Other
M129	Linoleum	Various Other Heterogeneous	Teased	None Detected		50% Cellulose 10% Synthetic	40% Other
M129A	Mastic	Gray/Black Non-Fibrous Homogeneous	Teased	None Detected		10% Cellulose	90% Other
M130	Linoleum	Various Other Heterogeneous	Teased	None Detected		50% Cellulose 10% Synthetic	40% Other
M130A	Mastic	Gray Non-Fibrous Homogeneous	Teased/Crushed	None Detected		10% Cellulose	90% Other
M131	Linoleum	Green/Black Other Heterogeneous	Teased/Dissolved	5% Chrysotile		45% Cellulose 5% Synthetic	45% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westmont, NJ
609-932-0900

Placitas, NJ
908-961-0550

Carle Place, NY
516-907-7251

Manhattan, NY
212-290-0052

Melbourne, FL
407-726-6223

Ann Arbor, MI
313-988-6810

San Mateo, CA
415-670-6401

Smyrna, GA
404-333-8068



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS
31A	Mastic	Brown Non-Fibrous Homogeneous	Teased		None Detected	5% Cellulose 5% Synthetic	90% Other
32A	Mastic	Brown Non-Fibrous Homogeneous	Crushed		None Detected	10% Cellulose	90% Other
33A	Mastic	Brown Non-Fibrous Homogeneous	Teased		None Detected	5% Cellulose	95% Other
34		Grey Fibrous Homogeneous	Teased/Crushed		55% Chrysotile	5% Cellulose	40% Other
35		Brown/Grey Other Heterogeneous	Crushed		None Detected	15% Cellulose	85% Other
36		Brown/Grey Other Heterogeneous	Crushed		None Detected	15% Cellulose	85% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. No. "# of Layers" refers to number of separable subsamples.
Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westport, NJ
908-863-0800

Piscataway, NJ
908-961-0550

Carle Place, NY
516-397-7251

Manhasset, NY
212-230-9052

Melbourne, FL
407-725-5223

Ann Arbor, MI
313-869-6810

San Mateo, CA
415-670-6401

Smyrna, GA
404-333-0282



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS			
				%	TYPE	%	FIBROUS	%	NONFIBROUS
M137		Brown/Grey Other Heterogeneous	Crushed		None Detected	15%	Cellulose	85%	Other
M138	Tile	White Non-Fibrous Homogeneous	Crushed/Dissolved	2%	Chrysotile	1%	Cellulose	97%	Other
M138A	MAstic	Black Non-Fibrous Homogeneous	Teased	5%	Chrysotile			95%	Other
M141		Grey Fibrous Homogeneous	Crushed		None Detected	15%	Cellulose	85%	Other
M142		Grey Fibrous Homogeneous	Crushed		None Detected	15%	Cellulose	85%	Other
M143		Grey Fibrous Homogeneous	Crushed		None Detected	15%	Cellulose	85%	Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow

David Buetow
Analyst

R. H. Maloney

Laboratory
Supervisor

Other Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.



Westport, NJ
908-652-4800

Florence, NJ
908-981-0550

Carle Place, NY
516-937-7261

Manhasset, NY
212-290-0052

Melbourne, FL
407-725-5223

Ann Arbor, MI
313-968-4810

San Mateo, CA
415-670-6401

Rayna, GA
404-333-6066



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
44		Grey Fibrous Homogeneous	Teased	55%	Chrysotile		45% Other
45	Paint	White Non-Fibrous Homogeneous	Ashed/Crushed		None Detected		100% Other
45A	White fabric	White Fibrous Homogeneous	Teased		None Detected	100%	Cellulose
45B	Tan paper layer	Tan Fibrous Homogeneous	Teased		None Detected	100%	Cellulose
46		Grey Non-Fibrous Homogeneous	Crushed		None Detected	50% Min. Wool	50% Other
47		Grey Non-Fibrous Homogeneous	Crushed		None Detected	50% Cellulose	50% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. " # of Layers" refers to number of separable subsamples.
Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R. K. Maloney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westmont, NJ
609-452-4308

Piscataway, NJ
908-961-0550

Carle Place, NY
516-997-7251

Manhattan, NY
212-290-0082

Melbourne, FL
407-725-6223

Ann Arbor, MI
313-468-6810

San Mateo, CA
415-670-6481

Smyrna, GA
404-333-6068



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS			
				%	TYPE	%	FIBROUS	%	NONFIBROUS
M148		Grey Non-Fibrous Homogeneous	Crushed		None Detected	45%	Cellulose	55%	Other
M149	Tile	Green Non-Fibrous Homogeneous	Crushed/Dissolved	8%	Chrysotile			92%	Other
M149A	Mastic	Black Non-Fibrous Homogeneous	Teased	10%	Chrysotile	2%	Cellulose	88%	Other
M152	Tile	Brown Non-Fibrous Homogeneous	Crushed/Dissolved	8%	Chrysotile			92%	Other
M152A	Mastic	Black Non-Fibrous Homogeneous	Teased	10%	Chrysotile			90%	Other
M155	Tile	Black Non-Fibrous Homogeneous	Teased	10%	Chrysotile			90%	Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.


Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Maloney
Laboratory
Supervisor

Other Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.



Westmont, NJ
908-953-6800

Piscataway, NJ
908-961-0550

Carle Place, NY
516-497-7251

Manhattan, NY
212-390-0052

Melbourne, FL
407-725-6223

Ann Arbor, MI
313-868-6810

San Mateo, CA
415-570-6401

Smyrna, GA
404-333-6066



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS			
				%	TYPE	%	FIBROUS	%	NONFIBROUS
55A	Mastic	Black Non-Fibrous Homogeneous	Teased		None Detected	2%	Cellulose	98%	Other
56A	Mastic	Black Non-Fibrous Homogeneous	Teased	10%	Chrysotile			90%	Other
58	Tile	Grey Non-Fibrous Homogeneous	Crushed/Dissolved	10%	Chrysotile			90%	Other
58A	Mastic	Black Non-Fibrous Homogeneous	Teased	10%	Chrysotile			90%	Other
61	Tile	Brown Non-Fibrous Homogeneous	Crushed/Dissolved	12%	Chrysotile			88%	Other
61A	Mastic	Black Non-Fibrous Homogeneous	Teased	20%	Chrysotile			80%	Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately.
c. "# of Layers" refers to number of separable subsamples.
d. Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R. K. Maloney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westport, NJ
908-963-4800

Piscataway, NJ
908-981-0550

Carle Place, NY
516-977-7251

Manhattan, NY
212-280-0082

Hollywood, FL
407-725-5223

Ann Arbor, MI
313-988-9810

San Mateo, CA
415-670-5401

Stuyvesant, GA
404-333-8066



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS			
				%	TYPE	%	FIBROUS	%	NONFIBROUS
M164	Tile	White Non-Fibrous Homogeneous	Crushed/Dissolved	2%	Chrysotile			98%	Other
M164A	Mastic	Black Non-Fibrous Homogeneous	Teased	5%	Chrysotile	5%	Cellulose	90%	Other
M167	Paint	Beige Non-Fibrous Homogeneous	Ashed/Crushed		None Detected			100%	Other
M167A	Ceiling tile	Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose		
M168	Paint	Beige Non-Fibrous Homogeneous	Ashed/Crushed		None Detected			100%	Other
M168A	Ceiling tile	Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose		

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.


David H. Buetow

David Buetow
Analyst

R. K. Mahoney

Laboratory
Supervisor

Other Approved
Signatory



Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westport, NJ
909-858-4800

Piscataway, NJ
908-981-0550

Carle Place, NY
516-987-7251

Manhattan, NY
212-290-0652

Melbourne, FL
407-426-6223

Ann Arbor, MI
313-669-8810

San Mateo, CA
415-870-5491

Smyrna, GA
404-333-9088



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
169	Paint	Beige Non-Fibrous Homogeneous	Ashed/Crushed		None Detected		100% Other
169A	Ceiling tile	Brown Fibrous Homogeneous	Teased		None Detected		100% Cellulose
170	Tile	Grey Non-Fibrous Homogeneous	Crushed/Dissolved	15%	Chrysotile		85% Other
170A	Mastic	Black Non-Fibrous Homogeneous	Teased	20%	Chrysotile		80% Other
173	Tile	Beige Non-Fibrous Homogeneous	Crushed/Dissolved	10%	Chrysotile		90% Other
173A	Mastic	Black Non-Fibrous Homogeneous	Teased	20%	Chrysotile	2% Cellulose	78% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. So, "# of Layers," refers to number of separable subsamples.
Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Maloney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westmont, NJ
609-858-1800

Piscataway, NJ
908-961-9850

Carle Place, NY
516-997-7251

Manhattan, NY
212-290-0662

Melbourne, FL
407-725-5223

Ann Arbor, MI
313-998-9810

San Mateo, CA
415-870-5401

Smyrna, GA
404-333-6098



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS			
				%	TYPE	%	FIBROUS	%	NONFIBROUS
M176	Tile	Red Non-Fibrous Homogeneous	Crushed/Dissolved	12%	Chrysotile	1%	Cellulose	87%	Other
M176A	Mastic	Black Non-Fibrous Homogeneous	Teased	15%	Chrysotile	3%	Cellulose	82%	Other
M179		White Non-Fibrous Homogeneous	Crushed		None Detected	20%	Cellulose	80%	Other
M180		White Non-Fibrous Homogeneous	Crushed		None Detected	20%	Cellulose	80%	Other
M181		White Non-Fibrous Homogeneous	Crushed		None Detected	20%	Cellulose	80%	Other
M182	White paper	White Fibrous Homogeneous	Teased	60%	Chrysotile	35%	Cellulose	3%	Other
				2%	Amosite				

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.
Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
182A	Brown paper	Black Fibrous Homogeneous	Teased		None Detected	100% Cellulose	
182B	Black paper	Black Fibrous Homogeneous	Teased		None Detected	98% Cellulose	2% Other
183		White Fibrous Homogeneous	Teased		15% Chrysotile	45% Min. Wool	40% Other
186		Grey Fibrous Homogeneous	Crushed		None Detected	65% Min. Wool	35% Other
187		Grey Fibrous Homogeneous	Crushed		None Detected	65% Min. Wool	35% Other
188		Grey Fibrous Homogeneous	Crushed		None Detected	60% Min. Wool	40% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. So, "# of Layers" refers to number of separable subsamples.
Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Worcester, NJ
603-553-4200

Hickory, NJ
908-981-0550

Carle Place, NY
516-997-7251

Manhattan, NY
212-260-0052

Melbourne, FL
407-726-5223

Ann Arbor, MI
313-462-6910

San Mateo, CA
415-670-6601

Smyrna, GA
404-333-6006



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS			
				%	TYPE	%	FIBROUS	%	NONFIBROUS
M189	Tile	Grey Non-Fibrous Homogeneous	Crushed/Dissolved	2%	Chrysotile			98%	Other
M189A	mastic	Black Non-Fibrous Homogeneous	Teased	10%	Chrysotile	2%	Cellulose	88%	Other
M192		Grey Other Homogeneous	Crushed		None Detected	15%	Cellulose	85%	Other
M193		Grey Other Homogeneous	Crushed		None Detected	10%	Cellulose	90%	Other
M194		Grey Other Homogeneous	Crushed		None Detected	10%	Cellulose	90%	Other
M195	Paint	Black Non-Fibrous Homogeneous	Teased		None Detected			100%	Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Maloney
Laboratory
Supervisor

Other Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.



Westmont, NJ
908-938-4800

Placataway, NJ
908-961-0550

Carle Place, NY
516-997-7261

Manhattan, NY
212-290-0062

Melbourne, FL
407-726-6223

Ann Arbor, MI
313-663-6810

San Mateo, CA
415-670-6461

Smyrna, GA
404-333-6066



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS			
				%	TYPE	%	FIBROUS	%	NONFIBROUS
195A	Woven layers	White Fibrous Homogeneous	Teased		None Detected	100%	Cellulose		
195B	Brown paper	Brown Fibrous Homogeneous	Teased		None Detected	100%	Cellulose		
195C	Black paper	Black Fibrous Homogeneous	Teased		None Detected	98%	Cellulose	2%	Other
195D	White paper	White Fibrous Homogeneous	Teased		None Detected	100%	Cellulose		
198	Paint	Black Non-Fibrous Homogeneous	Ashed/Crushed		None Detected			100%	Other
196A	Woven layers	White Fibrous Homogeneous	Teased		None Detected	100%	Cellulose		

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. No. "# of Layers" refers to number of separable subsamples. Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.L. Mahoney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westport, NJ
908-532-1000

Freezeway, NJ
908-981-0550

Carle Place, NY
516-987-7261

Manhattan, NY
212-230-0052

Maitland, FL
407-726-5223

Ann Arbor, MI
313-663-6810

San Mateo, CA
415-670-6401

Smyrna, GA
404-333-8066



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
M196B	Brown paper	Brown Fibrous Homogeneous	Teased	None Detected		100% Cellulose	
M196C	Black paper	Black Fibrous Homogeneous	Teased	None Detected		98% Cellulose	2% Other
M196D	White paper	White Fibrous Homogeneous	Teased	None Detected		100% Cellulose	
M197	Paint	Black Non-Fibrous Homogeneous	Ashed/Crushed	None Detected			100% Other
M197A	Woven layers	White Fibrous Homogeneous	Teased	None Detected		100% Cellulose	
M197B	Brown paper	Brown Fibrous Homogeneous	Teased	None Detected		100% Cellulose	

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.H. Mahoney
Laboratory
Supervisor

Other Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.



Westmont, NJ
609-633-1300

Piscataway, NJ
908-981-0500

Carle Place, NY
516-947-7251

Manhasset, NY
212-290-0052

Melbourne, FL
407-725-5223

Ann Arbor, MI
313-669-8810

San Mateo, CA
415-670-5491

Savannah, GA
404-333-6066



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
197C	Black paper	Black Fibrous Homogeneous	Teased	None Detected		98% Cellulose	2% Other
197D	White paper	White Fibrous Homogeneous	Teased	None Detected		100% Cellulose	
198		White Fibrous Homogeneous	Teased	40% Chrysotile			60% Other
201	Paint	White Non-Fibrous Homogeneous	Ashed/Crushed	None Detected		2% Min. Wool	98% Other
201A	Ceiling tile	Grey Fibrous Homogeneous	Teased	None Detected		65% Min. Wool 35% Cellulose	
202	Paint	White Non-Fibrous Homogeneous	Ashed/Crushed	None Detected		3% Min. Wool	97% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. so, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow

David Buetow
Analyst

R.K. Mahoney

Laboratory
Supervisor

Other Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.





Herrick Engineering Inc.
 1705 Chatsworth Lane
 Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS		
				%	TYPE	%	FIBROUS	%
M202A	Ceiling tile	Grey Fibrous Homogeneous	Teased	None Detected		70% Min. Wool 30% Cellulose		
M203	Paint	White Non-Fibrous Homogeneous	Ashed/Crushed	None Detected		2% Min. Wool	98% Other	
M203A	Ceiling tile	Grey Fibrous Homogeneous	Teased	None Detected		70% Min. Wool 30% Cellulose		
M204	Tile	Beige Non-Fibrous Homogeneous	Crushed/Dissolved	4% Chrysotile		1% Cellulose	95% Other	
M204A	Mastic	Black Non-Fibrous Homogeneous	Teased	10% Chrysotile		1% Cellulose	89% Other	
M207	Tile	Grey Non-Fibrous Homogeneous	Crushed/Dissolved	3% Chrysotile			97% Other	

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow

David Buetow
 Analyst

R.H. Mahoney

Laboratory
 Supervisor

Other Approved
 Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westmont, NJ
608-853-4900

Piscataway, NJ
908-961-0660

Carle Place, NY
516-397-7251

Manhasset, NY
212-290-0052

Maitheurus, FL
407-726-5223

Ann Arbor, MI
313-868-6310

San Mateo, CA
415-870-6401

Atlanta, GA
404-333-6068



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS			
				%	TYPE	%	FIBROUS	%	NONFIBROUS
07A	Mastic	Black Non-Fibrous Homogeneous	Teased	10%	Chrysotile			90%	Other
10	Tile	White Non-Fibrous Homogeneous	Crushed/Dissolved	3%	Chrysotile			97%	Other
10A	Mastic	Black Non-Fibrous Homogeneous	Teased	10%	Chrysotile	2%	Cellulose	88%	Other
13	Tile	White Non-Fibrous Homogeneous	Crushed/Dissolved	6%	Chrysotile	1%	Cellulose	93%	Other
13A	Mastic	Black Non-Fibrous Homogeneous	Teased	12%	Chrysotile	2%	Cellulose	86%	Other
16	Tile	White Non-Fibrous Homogeneous	Crushed/Dissolved		None Detected			100%	Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. No. of Layers refers to number of separable subsamples. Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R. L. Mahoney
Laboratory
Supervisor

Other Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.



Westport, NJ
908-358-4800

Piscataway, NJ
908-981-0550

Carle Place, NY
516-947-7251

Manhattan, NY
212-290-0062

Malbourne, FL
407-725-5223

Ann Arbor, MI
313-662-6810

San Mateo, CA
415-670-6401

Smyrna, GA
404-333-8068



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
M216A	Mastic	Black Non-Fibrous Homogeneous	Teased	None Detected		15% Cellulose	85% Other
M217	Tile	White Non-Fibrous Homogeneous	Crushed/Dissolved	None Detected			100% Other
M217A	Mastic	Black Non-Fibrous Homogeneous	Teased	None Detected		20% Cellulose	80% Other
M218	Tile	White Non-Fibrous Homogeneous	Crushed/Dissolved	None Detected		< 1% Cellulose	100% Other
M218A	Mastic	Black Non-Fibrous Homogeneous	Teased	None Detected		20% Cellulose	80% Other
M219	Tile	Tan Non-Fibrous Homogeneous	Crushed/Dissolved	4% Chrysotile		1% Cellulose	95% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Westmont, NJ
609-351-8800

Piscataway, NJ
908-981-0650

Carle Place, NY
516-997-7351

Manhattan, NY
212-290-0052

Melbourne, FL
407-725-5223

Ann Arbor, MI
313-989-4810

San Mateo, CA
415-670-5401

Smyrna, GA
404-333-8066



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, April 26, 1996

Ref Number: NC962692

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Correction Project No. 95120- Umstead Facility

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS			
				%	TYPE	%	FIBROUS	%	NONFIBROUS
19A	Mastic	Black Non-Fibrous Homogeneous	Teased	-	None Detected	5%	Cellulose	95%	Other
20A	Mastic	Black Non-Fibrous Homogeneous	Teased		None Detected	5%	Cellulose	95%	Other
21A	Mastic	Black Non-Fibrous Homogeneous	Teased		None Detected	2%	Cellulose	98%	Other
07A	Mastic	Black Non-Fibrous Homogeneous	Teased		15% Chrysotile	5%	Cellulose	80%	Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. The "# of Layers" refers to number of separable subsamples. Note: Sample- M107 (A) is at the end of report.

David H. Buetow
David Buetow
Analyst

R.K. Mahoney
Laboratory
Supervisor

Other Approved
Signatory



Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, May 03, 1996

Ref Number: GA96656

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Corrections/Umstead QC

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS
L990QC (FLOOR TILE)		Off-White/Grey Non-Fibrous Layers # 2	Dissolved	5%	Chrysotile	None Detected	95% Other
L990QC (MASTIC)		Black Non-Fibrous Layers # 2	Dissolved	5%	Chrysotile	None Detected	95% Other
M009QC (FLOOR TILE)		White/Green Non-Fibrous Layers # 2	Dissolved	3%	Chrysotile	None Detected	97% Other
M009QC (MASTIC)		Amber Non-Fibrous Layers # 2	Dissolved	None Detected		< 1% Cellulose	100% Other
M021QC		Pink Fibrous Homogeneous	Dissolved	15%	Chrysotile 15% Amosite	None Detected	70% Other
M037QC (FLOOR TILE)		Off-White/Grey Non-Fibrous Layers # 2	Dissolved	10%	Chrysotile	None Detected	90% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.


Craig Coombs
Analyst

Laboratory
Supervisor

Other Approved
Signatory



Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for its accuracy of results when requested to physically separate and analyze layered samples.



Herrick Engineering Inc.
1705 Chatsworth Lane
Raleigh, NC 27614

Friday, May 03, 1996

Ref Number: GA96656

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Corrections/Umstead QC

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS % NONFIBROUS
M179QC		White Fibrous Homogeneous	Dissolved	None Detected		10% Cellulose	90% Other
M201QC		White/Grey Fibrous Heterogeneous	Dissolved	None Detected		40% Cellulose 50% Min. Wool	10% Other
M216QC (FLOOR TILE)		Off-White Non-Fibrous Layers # 2	Dissolved	None Detected		None Detected	100% Other
M216QC (MASTIC)		Black Non-Fibrous Layers # 2	Dissolved	None Detected		10% Cellulose	90% Other
M219QC (FLOOR TILE)		Off-White/Grey Non-Fibrous Layers # 2	Dissolved	10% Chrysotile		None Detected	90% Other
M219QC (MASTIC)		Black Non-Fibrous Layers # 2	Dissolved	None Detected		< 1% Cellulose	100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

Craig Coombs
Analyst

Laboratory
Supervisor

Other Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.





Herrick Engineering Inc.
 1705 Chatsworth Lane
 Raleigh, NC 27614

Friday, May 03, 1996

Ref Number: GA96656

POLARIZED LIGHT MICROSCOPY (PLM)

Project: NC Dept. of Corrections/Umstead QC

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	%	FIBROUS
4037QC (MASTIC)		Black Non-Fibrous Layers # 2	Dissolved	10%	Chrysotile	None Detected	90% Other
4082QC		Pink Fibrous Homogeneous	Dissolved	15%	Chrysotile 15% Amosite	None Detected	70% Other
4128QC (INOLEUM)		White/Grey/Black Fibrous Layers # 2	Dissolved	None Detected		30% Cellulose 10% Synthetic	60% Other
4128QC (MASTIC)		Brown Non-Fibrous Layers # 2	Dissolved	None Detected		5% Cellulose	95% Other
4141QC		White Fibrous Homogeneous	Crushed/Dissolved	None Detected		10% Cellulose	90% Other
4167QC		White/Beige Fibrous Heterogeneous	Teased	None Detected		90% Cellulose	10% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.


 Craig Coombs
 Analyst

Laboratory
 Supervisor

Other Approved
 Signatory



Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Floor tiles and wipes should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in full with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.



STATE OF NORTH CAROLINA
 OFFICE OF STATE PERSONNEL
 116 WEST JONES STREET
 RALEIGH 27603-8004

JAMES B. HUNT, JR.
 GOVERNOR

RONALD G. PENNY
 STATE PERSONNEL DIRECTOR

February 3, 1998

TO: Joe Simpson, Safety and Health Director
 Department of Correction

FROM: Mary Fulmer, Accredited Asbestos Inspector #10546 MF
 Risk Control Services, OSP

SUBJECT: Asbestos Inspection of the Umstead Laundry Building and Heat
 Reclamation Building on January 23, 1998

Chrysotile asbestos was detected in bulk samples of these materials in the Umstead Laundry Building and Heat Reclamation Building:

Sample # 4. Grey floor tile in the processing assistant's office and in the manager's office (2%)

Sample # 5. Black mastic on the grey floor tile in the processing assistant's office and in the manager's office (5%)

No asbestos was detected in bulk samples of these materials:

Samples 1 and 1A. Wall surfacing material (white paint and tan plaster and grey coat) in the processing assistant's and in the manager's office

Sample 2. Black backing on the wall surfacing material (plaster) in the processing assistant's office and in the manager's office

Sample 3. Black coating on the interior side of the brick wall in the processing assistant's office and in the manager's office

Sample 6. Brown and white ceiling tile in the processing assistant's office and in the manager's office

Sample 7. Paint and cloth wrapping on fiberglass thermal system insulation on the steam distribution line behind dryers 1-5

Sample 8. Wrapping and mud on fiberglass thermal system insulation on the inlet steam line going into dryers 1-5

Directors Office	733-7108	PMIS	733-2992	Employee Practices	733-7922	Equal Opportunity Services	733-0205
Commission Staff	733-7112	Employee Assistance	733-8545	Temporary Solutions	733-7927	Position Management	733-3182
Administrative Services	733-7934	Employee & Mgmt Dev	733-2474	Employee Safety & Health	733-6316	Performance Management	733-7108

An Equal Opportunity Employer

Sample 9. Grey mud on fittings on the steam distribution line behind washers 1-5

Sample 10. Grey insulation on the front and back of the hot water heater in the heat reclamation building

Sample 11. Brown mud from joint on the hot water pipes in the heat reclamation building

Sample 12. Paint and cloth wrapping on mudded joint on the hot water pipes in the heat reclamation building

Sample 13. White insulation on hot water pipe in the heat reclamation building

Sample 14. White wrapping on hot water pipe in the heat reclamation building

Sample 15. Black wrapping on fiberglass insulation on steam pipes in crawl space under hand presses in the laundry building

The samples were analyzed by EMSL Analytical, Inc. The laboratory report is attached.

cc: Randy Penland, NC Department of Correction Enterprise Laundries, 2020
Yonkers Road, Raleigh, NC 27604

RECEIVED

FEB 05 '98

DOC SAFETY OFFICE

EMSL Analytical, Inc.

620-G Guilford College Rd
Greensboro, NC 27409

Phone: (336) 297-1487 Fax: (336) 297-1676



Attn.: Joe Simpson
North Carolina Office of State Personnel
116 W. Jones
Raleigh, NC 27603-8004

Monday, February 02, 1998

Ref Number: NC98285

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: Umstead Laundry Bldg & Heat Reclamation Bldg

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
1	Paint & Plaster	Tan/White Non-Fibrous Heterogeneous	Teased		None Detected		100% Other
1A	Grey Coat	Gray Non-Fibrous Homogeneous	Teased		None Detected		100% Other
2		Black Non-Fibrous Homogeneous	Dissolved/Teased		None Detected		100% Other
3		Black Non-Fibrous Homogeneous	Dissolved/Teased		None Detected		100% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 199-1 Method

Tom Ferrante
Tom Ferrante
Analyst

R.K. Mahoney
Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in part with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.



EMSL Analytical, Inc.

620-G Gullford College Rd
Greensboro, NC 27409
Phone: (336) 297-1487 Fax: (336) 297-1676



Attn.: Joe Simpson
North Carolina Office of State Personnel
116 W. Jones
Raleigh, NC 27603-8004

Monday, February 02, 1998

Ref Number: NC98285

POLARIZED LIGHT MICROSCOPY (PLM)
Performed by EPA 600/R-93/116 Method*

Project: Umstead Laundry Bldg & Heat Reclamation Bldg

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
4		Grey Non-Fibrous Homogeneous	Dissolved/Teased	2%	Chrysotile		98% Other
6		Black Fibrous Homogeneous	Dissolved/Teased	5%	Chrysotile	2% Cellulose < 1% Glass	93% Other
6		Brown/White Fibrous Heterogeneous	Teased		None Detected	98% Cellulose	2% Other
7	Paint & Cloth	Various Fibrous Heterogeneous	Teased		None Detected	60% Cellulose	40% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately.
Also, "# of Layers" refers to number of separable subsamples.
* NY samples also analyzed by ELAP 198-1 Method

Tom Ferrante
Tom Ferrante
Analyst

R.H. Maloney
Approved
Signatory

Disclaimers: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in part with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Analytical performed by EMSL Greensboro (336) 297-1487 and Durham (919) 286-1000

EMSL Analytical, Inc.620-G Guilford College Rd
Greensboro, NC 27409

Phone: (336) 297-1487 Fax: (336) 297-1676

EMSLAttn.: Joe Simpson
North Carolina Office of State Personnel
116 W. Jones
Raleigh, NC 27603-8004

Monday, February 02, 1998

Ref Number: NC98285

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: Umstead Laundry Bldg & Heat Reclamation Bldg

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
8	Wrap & Mud	Various Fibrous Heterogeneous	Teased	None Detected		40% Cellulose 20% Glass 10% Min. Wool	30% Other
9		Grey Fibrous Homogeneous	Teased	None Detected		40% Glass 10% Min. Wool	50% Other
10		Grey Fibrous Homogeneous	Teased	None Detected		40% Glass 10% Min. Wool	50% Other
11		Brown Fibrous Homogeneous	Teased	None Detected		70% Cellulose 20% Glass 5% Min. Wool	5% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "% of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method



Tom Ferrante
Analyst



Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with either SEM or TEM. The above test report relates only to the items tested. This report may only be reproduced in part with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Analysis performed by EMSL, Greensboro, North Carolina. Page 03 of 03.

EMSL Analytical, Inc.620-G Gailford College Rd
Greensboro, NC 27409

Phone: (336) 297-1487 Fax: (336) 297-1676

EMSLAttn.: Joe Simpson
North Carolina Office of State Personnel
116 W. Jones
Raleigh, NC 27603-8004

Monday, February 02, 1998

Ref Number: NC98285

POLARIZED LIGHT MICROSCOPY (PLM)

Performed by EPA 600/R-93/116 Method*

Project: Umstead Laundry Bldg & Heat Reclamation Bldg

SAMPLE	LOCATION	APPEARANCE	SAMPLE TREATMENT	ASBESTOS		NONASBESTOS	
				%	TYPE	% FIBROUS	% NONFIBROUS
12	Paint & Cloth	Various Fibrous Heterogeneous	Teased	None Detected		70% Cellulose	30% Other
13		White Fibrous Homogeneous	Teased	None Detected		30% Cellulose	70% Other
14		White Fibrous Homogeneous	Teased	None Detected		100% Cellulose	
15		Black Fibrous Homogeneous	Dissolved/Teased	None Detected		25% Cellulose	75% Other

Comments: For all obviously heterogeneous samples easily separated into subsamples, and for layered samples, each component is analyzed separately. Also, "# of Layers" refers to number of separable subsamples.

* NY samples also analyzed by ELAP 198-1 Method

Thomas Ferrante
Tom Ferrante
Analyst

R. H. Mahoney
Approved
Signatory

Disclaimer: PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Thus negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with either SEM or TEM. This above test report relates only to the items tested. This report may only be reproduced in part with written approval by EMSL. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. All "NVLAP" reports with NVLAP logo must contain at least one signature to be valid. Laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples.

Analyte performed by EMSL Greensboro, NVLAP # 1992-10-1

UMSTEAD CORRECTIONAL CENTER Butner, NC

Roof Condition Report


Inspection Date: 08/22/2019

PREPARED BY:



Tal Eidson
PO Box 991
Kinston, NC 28502
tal@curtiscc.com
910-992-1180

PREPARED FOR:



Reid Daniel
Director
Town of Butner
rdaniel@butnenc.org. Phone:
919-691-0095



FACILITY INFORMATION:


Umstead Correctional Facility
400 West D Street
Butner, NC 27509
Building Type: Dormitory/detention
Neighborhood: Open Terrain

This report was prepared using True Roof Rater by



UMSTEAD CORRECTIONAL CENTER - BUTNER, NC

Roof Repair/Replacement Costs



ROOFTOP SUMMARY:

Roof Sections: 1
 Total Issues: 19
 Total Details: 2

Section	Severity	Recommendation	Repair Cost	Replacement Cost
A)	Major	Replace	N/A	N/A
			\$0.00	\$0.00


Disclaimer

This report has been prepared by an individual trained by experience and education in this industry. However, this report is not intended to be and does not constitute an expert opinion on the cause of any deficiencies found, rather it addresses such deficiencies, if found, and proposed corrective action to restore the effectiveness and long term viability of the roof. This report was not prepared by a licensed professional engineer and is not intended to be a statement or opinion concerning the quality of the installation inspected, since its focus is on remediation of any conditions found. This report is for the exclusive use for the recipient and may not be used by any other person or entity without the prior express consent of the author.

Notice: Scale drawings, preliminary specifications and documentation provided by are preliminary. The successful bidder is responsible for all building permits, field conditions and compliance with building codes. Any budgetary figures are preliminary only and not guaranties. Preliminary specifications and budgeting parameters are based upon field inspections and test cuts when applicable and are subject to revisions based upon final field conditions and construction issues. The successful bidder is responsible to conduct their own field tests and construction inspections to assure proper installation and compliance with building codes. No structural analysis has been provided in these preliminary specifications.

Versico nor their independent representatives are architects and therefore it is not the intent herein to describe all of the details for roofing and flashing. The roofing contractors shall assure themselves that they have been provided with all information and details required by the membrane manufacturer or project conditions to achieve a complete water-tight installation regardless of whether or not such information or details are expressed specifically herein. The roofing contractor shall provide immediate notice to the owner in the event the roofing contractor determines that additional information, details or drawings are necessary to achieve a complete watertight installation. All work shall be performed by the roofing contractor in accordance with local, state and federal laws, codes and regulation. Owner shall accept responsibility for the adequacy of the design and the conformance of the design with all local, state, federal laws, codes. To the extent applicable, Owner accepts responsibility for any identification, analysis removal and disposal of asbestos containing material.

Section A Overview:



Section Outcome:

Replace

Severity:

Major

Section Summary:

Section Issues: 19

Section Details: 2

Section Recommendation:

This roof system is over 20 years old. The system is in the downward trend of its life-cycle. Typically a gravel built-up system will show signs of deterioration at the perimeter edges and penetrations. This system is a product of these phenomenons. Facia, soffit, and wall restoration will also be required to create a watertight building envelope. Our recommendation is to invest in a new roof system before any building improvements are made. Normal maintenance has not been conducted and there are deficiencies and leaks throughout the roof area.

Section A:

Detail AD-1: Overview of front-side - main roof area

Detail:

Overview of front-side - main roof area

Description:

Front-side roof area.




Figure 1



Figure 2

Section A:

Detail AD-2: Roof Composition

Detail:
Roof Composition

Description:
Image of roof composition (2.5") over concrete deck.




Figure 1



Figure 2

Section A:

Issue AI-1: Alligatoring

Description:

The cracking of the surfacing bitumen asphalt which occurs during the aging process in which the loss of volatile oils and the oxidation brought about by solar radiation; produces a pattern of cracks similar to an alligator's hide. The cracks may or may not extend through the surfacing bitumen.

Why is this an issue?

When alligatoring cracks extend through the entire waterproofing surface, the underlying felts can become exposed to moisture, which will progressively cause the strength in the felts to decrease. Splitting of the roof membrane may result.

Severity:

Moderate

Action:

Requires Repair





Figure 1



Figure 2



Figure 3

Section A:

Issue AI-2: Alligatoring

Description:

The cracking of the surfacing bitumen asphalt which occurs during the aging process in which the loss of volatile oils and the oxidation brought about by solar radiation; produces a pattern of cracks similar to an alligator's hide. The cracks may or may not extend through the surfacing bitumen.

Why is this an issue?

When alligatoring cracks extend through the entire waterproofing surface, the underlying felts can become exposed to moisture, which will progressively cause the strength in the felts to decrease. Splitting of the roof membrane may result.

Severity:

Moderate

Action:

Requires Repair





Figure 1




Figure 2

Section A:

Issue AI-3: Vegetation

Description:

A roof top environment that is rich with moisture and air born dirt and particulates can be the breeding ground for seeds.

Why is this an issue?

These seeds can grow into vegetation with root structures that can penetrate and rupture the strongest of roof membranes, resulting in leakage into the roof system and the building's interior.

Severity:

Moderate

Action:

Requires Repair




Figure 1



Figure 2

Section A:

Issue AI-4: Clogged drain

Description:

Foreign objects clogging the drain strainer or drain bowl.

Why is this an issue?

Clogged drains impede positive drainage and result in the development of ponding water conditions. Additional water adds weight to the roofing system. This condition requires immediate correction. In its extreme, this could result in deck deflection or roof collapse.

Severity:

Major

Action:

Requires Repair




Figure 1

Section A:

Issue AI-5: Skylight/Curb Damaged

Description:

Broken skylights throughout the roof areas. Open void in roof system/building.

Why is this an issue?

Water intrusion is occurring. Interior is compromised.

Severity:

Major

Action:

Requires Repair




Figure 1

Section A:

Issue AI-6: Drain broken strainer

Description:

Drains are installed with strainers to prevent debris and other foreign objects from entering the piping system.

Why is this an issue?

Broken or missing roof drain strainers may allow dirt and debris into roof drains. This condition may clog or impede drainage causing ponding water on the roof. If the roof membrane or drain flashing is compromised in a ponding area, the water may drain into the roof system and into the building.

Severity:

Major

Action:

Requires Repair




Figure 1

Section A:

Issue AI-7: Open siding

Description:

Open siding allows driving rain and snow to enter the building.

Why is this an issue?

Building wall siding must be watertight and sealed from driving rain and snow. Open siding allows moisture and water to enter the building or roof system, causing deterioration and failure of insulation substrates and interior finishes.

Severity:

Major

Action:

Requires Repair




Figure 1

Section A:

Issue AI-8: Clogged drain

Description:

Foreign objects clogging the drain strainer or drain bowl.

Why is this an issue?

Clogged drains impede positive drainage and result in the development of ponding water conditions. Additional water adds weight to the roofing system. This condition requires immediate correction. In its extreme, this could result in deck deflection or roof collapse.

Severity:

Major

Action:

Requires Repair




Figure 1



Figure 2

Section A:

Issue AI-9: Broken Skylight

Description:

Skylight/curb is damaged. Open void to building's interior.

Why is this an issue?

Water intrusion is occurring. Building's interior is compromised.

Severity:

Major

Action:

Requires Repair




Figure 1

Section A:

Issue AI-10: Open siding

Description:

Open siding allows driving rain and snow to enter the building.

Why is this an issue?

Building wall siding must be watertight and sealed from driving rain and snow. Open siding allows moisture and water to enter the building or roof system, causing deterioration and failure of insulation substrates and interior finishes.

Severity:

Major

Action:

Requires Repair




Figure 1

Section A:

Issue AI-11: Ponding


Description:

Ponding water can be traced to any of several factors. First, a roof may pond water as a result of poor housekeeping on the roof which contributes to clogged drains, gutters and downspouts. The build up of roof top debris or displaced gravel ballast frequently blocks water flow and creates ponds. Secondly, the building's roof top drainage system may not have been designed properly. Finally, ponds form as a result of such common conditions as building settlement and deck deflection.

Why is this an issue?

The NRCA has classified "undesirable" ponding water as standing for more than 48 hours, though ponding can pose a threat in even shorter time spans. Since ponds occur in low areas of a roof, a pond becomes a repository for debris, sediment, and chemical

emissions. Ponding encourages microorganism and bacterial degradation, roof deflection, magnified ultraviolet exposure and premature failure of the roof system. A matter of "deep" concern in the roofing industry is the fact that a 1" deep pond weighs 5.2 lbs. / sq. ft. and many structures cannot handle this extra load.



Severity:

Major

Action:

Requires Repair



Figure 1

Section A:


Issue AI-12: Ponding

Description:

Ponding water can be traced to any of several factors. First, a roof may pond water as a result of poor housekeeping on the roof which contributes to clogged drains, gutters and downspouts. The build up of roof top debris or displaced gravel ballast frequently blocks water flow and creates ponds. Secondly, the building's roof top drainage system may not have been designed properly. Finally, ponds form as a result of such common conditions as building settlement and deck deflection.

Why is this an issue?

The NRCA has classified "undesirable" ponding water as standing for more than 48 hours, though ponding can pose a threat in even shorter time spans. Since ponds occur in low areas of a roof, a pond becomes a repository for debris, sediment, and chemical emissions. Ponding encourages microorganism and bacterial degradation, roof deflection, magnified ultraviolet exposure and premature failure of the roof system. A matter of "deep" concern in the roofing industry is the fact that a 1" deep pond weighs 5.2 lbs. / sq. ft. and many structures cannot handle this extra load.



Severity:

Moderate

Action:

Requires Repair



Figure 1



Figure 2

Section A:

Issue AI-13: Drain broken strainer

Description:

Drains are installed with strainers to prevent debris and other foreign objects from entering the piping system.

Why is this an issue?

Broken or missing roof drain strainers may allow dirt and debris into roof drains. This condition may clog or impede drainage causing ponding water on the roof. If the roof membrane or drain flashing is compromised in a ponding area, the water may drain into the roof system and into the building.

Severity:

Major

Action:

Requires Repair




Figure 1

Section A:

Issue AI-14: Open siding

Description:

Open siding allows driving rain and snow to enter the building.

Why is this an issue?

Building wall siding must be watertight and sealed from driving rain and snow. Open siding allows moisture and water to enter the building or roof system, causing deterioration and failure of insulation substrates and interior finishes.

Severity:

Major

Action:

Requires Repair



Figure 1



Figure 2

Section A:

Issue AI-15: Debris

Description:

Any foreign objects on the surface of the roof. These foreign objects could include vegetation such as dead leaves and man made objects such as broken glass, nails, etc.

Why is this an issue?

The buildup of rooftop debris frequently impedes positive drainage, clogs drains and results in the development of ponding water conditions. In its extreme, this could result in roof collapse. Sharp foreign objects can puncture a roof membrane if stepped upon, resulting in wet insulation, roof leaks and interior damage.

Severity:

Major

Action:

Requires Repair




Figure 1



Figure 2

Section A:

Issue AI-16: Alligatoring

Description:

The cracking of the surfacing bitumen asphalt which occurs during the aging process in which the loss of volatile oils and the oxidation brought about by solar radiation; produces a pattern of cracks similar to an alligator's hide. The cracks may or may not extend through the surfacing bitumen. This is typical of the majority of curbs throughout the roof area.

Why is this an issue?

When alligatoring cracks extend through the entire waterproofing surface, the underlying felts can become exposed to moisture, which will progressively cause the strength in the felts to decrease. Splitting of the roof membrane may result.

Severity:

Major

Action:

Requires Repair





Figure 1



Figure 2

Section A:

Issue AI-17: Open siding

Description:

Open siding allows driving rain and snow to enter the building.

Why is this an issue?

Building wall siding must be watertight and sealed from driving rain and snow. Open siding allows moisture and water to enter the building or roof system, causing deterioration and failure of insulation substrates and interior finishes.

Severity:

Major

Action:

Requires Repair




Figure 1



Figure 2

Section A:

Issue AI-18: Flashing defect - crazed and cracked

Description:

Flashings exhibit a crazed or cracked appearance in the top layer of the flashings surface. Extended exposure to UV rays over time causes the flashing to split.

Why is this an issue?

Splits permit water entry into the roofing system and potentially into the building interior.

Severity:

Major

Action:

Requires Repair




Figure 1



Figure 2

Section A:

Issue AI-19: Masonry deterioration

Description:

Open masonry wall and coping mortar joints resulting from wall movement, disbonding, cracked or deteriorated mortar. Masonry wall and coping mortar joints are the most common means of water entry into a masonry wall.

Why is this an issue?

Water penetration is responsible for many of the problems in masonry walls. If a wall is saturated with water, freezing and thawing may cause cracking, spalling, and disintegration. Water and moisture can cause masonry to experience dimensional changes, metal to corrode, insulation to lose its effectiveness, interior finishes to deteriorate and efflorescence to appear on exterior surfaces.

Severity:

Major

Action:

Requires Repair





Figure 1



PO Box 991
Kinston, NC 28502

T 252.523.1078
F 252.523.6151

CurtisCC.com

August 23rd, 2019

BUDGET/ESTIMATE FOR RE-ROOF

Town of Butner
Public Works
403 West G Street
Butner, NC 27509

**Attention: Reid Daniel
Director**

**Reference: Umstead Correctional Facility – Roof Assessment & Re-Roofing
Budgetary Figure**

Reid,

We propose to provide the labor, material, taxes, insurance, equipment, permits and supervision to provide the following scope of work:

Roof System Details

- Demo existing roof system down to the concrete decking. Any work-related debris will be disposed of in local County landfill.
- Install vapor barrier over existing concrete deck.
- Fully adhere polyisocyanurate insulation board (insulation system/design to be determined).
- Fully adhere a 36-mil FiberTite membrane roof as per Manufacturer's details and instructions per building specific wind uplift calculations and to meet NC Building Code requirements.
- Flash all perimeters and penetrations as per Manufacturer's details and instructions. At existing parapet walls, new membrane will be terminated at existing coping with new counter-flashing.
- Fabricate and install counter-flashing from 24-gauge pre-finished steel. Standard colors only.

See Page 2

- Upon completion and final acceptance, a Contractor's (2) year warranty will be issued in conjunction with a Manufacturer's Total System (25) year warranty.

All for the sum of.....\$575,000.00

This information is only for budget/planning. A formal proposal will be provided upon request.

Sincerely,



Tal Eidson
Business Development
Curtis Construction Company, Inc.

Budgeted Roof Area





BUDGET PROPOSAL

D. H. GRIFFIN WRECKING CO., INC.
 421 RALEIGH VIEW ROAD, RALEIGH, NC 27610
 PHONE 919-772-4711 FAX 919-772-4311
www.dhgriffin.com - License # 35452

PROPOSAL TO: HagerSmith Design

DATE: January 27, 2012

ATTN: Tony Conner

DHGW Proposal #: 1950-120

JOB NAME: Correctional Facility Demolition

LOCATION: 400 West D St., Butner, NC

Direct: 919-838-5104

EMAIL: tconner@hagersmith.com

Based on site inspection and verbal descriptions, D. H. Griffin Wrecking Co., Inc. (DHGW) proposes the following scope of services:

1. Provide necessary labor, equipment, trucking, disposal cost, materials, insurance, etc. to perform work as indicated.
2. DHGW will demolish and dispose of materials off site in accordance with local, state and federal regulations.
3. Coordinate all utility disconnects with the appropriate agencies
4. Apply for and secure the Town of Butner demolition permit when approved
5. Remove Freon as mandated by state regulations
6. File required *National Emission Standards for Hazardous Air Pollutants* (NESHAP) forms ten (10) working days prior to commencement of any work related activities as mandated by state and federal law.
7. Demolish and dispose of the existing buildings (main, gym, & maintenance) complete with slabs grade beams and footers.
8. Remove and dispose of asphalt paving.
9. Rough grade areas utilizing on site material

We propose hereby to perform the work as listed above for the BUDGET lump sum amount of: Six Hundred Ninety-Five Thousand Dollars (\$695,000.00) **

Project Clarification:

** Owner to provide water and electrical for abatement**

** Owner to provide abatement design, air monitoring, and clearance**

** Building demolition includes the removal of slabs, grade beams, and footers**

** Price includes one (1) mobilization**

** Engineering layout if required is by others**

** The above quote is based on working Monday – Friday **

** Any delays or stoppages of work will be handled as an extra cost incurred by DHGW and will be invoiced to the owner or general contractor at an hourly or daily rate on equipment and labor**

DHGW does exclude the following items:

- Removal of underground utilities
- Protection and/or replacement of driveways and sidewalks that are to remain
- Demolition and/or removal of above and/or below ground items other than the above-mentioned
- Removal and/or protection of fences, trees and shrub
- Relocation, evacuation, disconnection, rerouting, capping, locating and marking of utilities within the demolition limits or protection of unmarked utilities within the limits of demolition
- Sediment or erosion control, tree protection, construction/ security fences and barricades
- Backfill and compaction
- Removal and disposition of any hazardous or asbestos materials, including paint, except those items, if any, which are described and itemized above, whether concealed or not.
- Identification or removal of underground storage tanks (USTs) or their contents, removal of tires, and oil
- Cost of performance and payment bonds (*can be provided at an additional cost*)
- Signs and/or barricades

DHGW retains salvage rights to materials under contract.

If awarded contract, DHGW requests that a signed copy of this proposal become part of contract documents.

Payment to be made as follows: **Upon Completion or Monthly Progress Billings**

All payments are due and payable as noted. Whenever retainage is required to be withheld, upon completion of D.H. Griffin Wrecking Company, Inc.'s (DHGW) scope of work (contract or sub-contract) DHGW will issue an invoice for work performed and a separate final invoice for retainage. All retainage is to be paid in full no later than forty-five (45) days from date of final invoice. Should the project duration exceed thirty (30) days monthly progress billings will be submitted and paid within thirty (30) days of submission. The undersigned further

agrees to pay to D.H. Griffin Wrecking Company, Inc., a reasonable attorney's fee if the obligation evidenced hereby be collected by an attorney-at-law after maturity. Any alteration or deviation from above specifications involving extra costs will be executed only upon written orders, and will become an extra charge over and above the estimate.

Authorized Signature: *Ed Blount*

NOTE: This proposal may be withdrawn by DHGW if not accepted within 30 days of above date.

Ed Blount – Estimator; Mobile # 919-427-2174 // eblount@dhgriffin.com

PLEASE SIGN, DATE AND RETURN ORIGINAL

Acceptance of Proposal – *The above prices, specifications and conditions are satisfactory and are hereby accepted. You are **authorized to do the work as specified. Payment will be made as outlined above.***

Signature

Name and Title

Date of Acceptance



www.dhgriffin.com